



# 5 PRO

## 261 MP Series

### Owner's Manual



[www.canaweld.com](http://www.canaweld.com)

# Thank You

From

# Canaweld

Thank you for choosing a Canaweld machine, with 40+ years of welding equipment manufacturing experience overseas, you can feel confident that you have made the right choice.

**Since the 1980s**, the founders of Canaweld have been actively involved in research & development, production and sales within the welding and cutting industries. They have filed countless patents and set new standards in the welding industry.

For over a decade the founders of Canaweld, have been members of the Technical Committee (TC 26) of the **International Electro-technical Commission (IEC)**. **IEC** is the world's leading organization on international standards for all electrical, electronic, and related technologies.

The company has also been an **expert member of the Canadian Standards Association (CSA), within the Technical Committee, responsible for Canadian standards of welding and cutting machines.**

Canaweld was created with the aim of providing our customers with advanced technologies. Our products, from design to assembly, are created with years of experience in research & development, materials engineering, quality control and testing.

Canaweld machines are among the best in the world in terms of quality.

The materials used in our designs are some of the best available on the market.

We believe in the high performance of our equipment and, therefore, offer a 3-year warranty.

We use strict test procedures, and our expectations exceed the required standards. For example, according to International Standards, machines must be tested at 40°C (104°F), but Canaweld tests the machines at both 40°C and 50°C (122°F). In doing so, we ensure that our machines will continue to operate even in hot climates.

Finally, all machines are only packaged and shipped when they pass strict mandatory tests.

**This user manual should be read carefully to fully understand the machine you have purchased and how to maintain it in the best operating condition.**

For more information on our full line of products please visit our website or contact a dealer in your local area, our dealer list can be found on our website: [www.canaweld.com](http://www.canaweld.com)

## Table of Contents

☐Safety precautions & Symbols (English) .....	1
☐Précautions de sécurité et les symboles (French)....	6
☐Introduction.....	11
☐Description .....	11
☐Technical Data.....	12
☐Usage Limits (IEC 60974-1).....	12
☐How to Lift Up the Machine.....	12
☐Open the Packaging .....	13
☐Installation and connections.....	13
☐Connecting the welding machine to the utility line..	13
☐Connection to Generator .....	14
☐Front and Rear Panel Layout of Welding Machine.	14
☐Front Panel Functions and Descriptions .....	15
☐JOB Program Control Panel .....	19
☐Instructions for Saving, Activating, and Deleting Memory Channels.....	19
☐MIG-MAG Techniques .....	19
☐Preparing the MIG Welder for Operation.....	22
☐Wire Feed Roller Selection .....	24
☐Wire Installation and Set Up Guide .....	25
☐MIG Torch Liner Installation.....	26
☐MIG Torch Liner Types and Information.....	26
☐Recommendations for Gas Selection and Adjustment for MIG Process.....	27
☐TIG Welding Procedure .....	28
☐Installation & Operation for TIG Welding.....	34
☐Recommendations for Gas Selection and Adjustment for TIG Process .....	35
☐Stick Welding Procedure .....	36
☐SMAW Welding: Installation & Operation.....	37
☐Welding Circuit: Cables, and Connections .....	38
☐Accessing Welding Machine Settings .....	38
☐Maintenance .....	38
☐Troubleshooting Table .....	39
☐Common Welding Problems .....	40
☐Welding Machine Error Codes .....	43
☐Meaning of graphic symbols on machine .....	43
☐Wiring Diagram.....	44

## ☐ Safety precautions & Symbols (English)

### 1.1 General Safety Precautions

Users of Canaweld welding and plasma cutting equipment are ultimately responsible for ensuring that everyone working on or around the equipment follow all safety measures. Safety precautions must fulfill the criteria for welding or plasma cutting equipment of this sort. In addition to the usual workplace laws, the following guidelines should be followed. To keep yourself and others safe, read, obey, and save these critical safety warnings and operating instructions. You are entirely responsible for the Product's safe operation. Canaweld does not and cannot give any assurances or warranties about the product's safety in your environment. This device is not designed for use in residential areas where the electrical power comes from a public low-voltage supply source. Due to both conducted and radiated disturbances, it may be challenging to ensure electromagnetic compatibility of the equipment in certain regions. This product is only for removing metal. Any other usage might result in bodily harm and/or damage to the equipment. In the event of a malfunction, contact a professional for assistance.

All work must be done by skilled employees who are familiar with how the welding or plasma cutting equipment works. Incorrect equipment operation can lead to dangerous circumstances, resulting in harm to the operator and equipment damage. Anyone who works with welding or plasma cutting equipment should understand how it works, where the emergency stops are situated, what safety measures should be followed, and how to utilize plasma cutting and/or welding.

Use approved personal safety equipment, such as safety glasses, flame-resistant clothes, and safety gloves. Avoid wearing scarves, bracelets, rings, and other loose-fitting items that may become stuck or cause burns. The operator must guarantee that no unauthorized personnel are present in the equipment's working area when it is turned on and no one is exposed to the arc when it is struck. The work environment must be free from drafts and appropriate for the job. The return cable must be securely connected and working on high voltage equipment must be done by a qualified electrician only. A proper and clearly marked fire extinguishing equipment must be close at hand. While the equipment is in operation, do not lubricate or maintain it.

### 1.2 Safety Precautions & Symbol



**Before working on the machine, read the owner's manual.**

Read the safety information at the beginning of the manual. To fully understand the machine's capabilities and safety measures, read this manual

thoroughly. Follow the Owner's Manuals, industry standards, and national, province, state, and local requirements.



#### **DANGER!**

The symbol indicates a dangerous action that will result in death or serious injury if not prevented.

The potential dangers or hazards are depicted in the symbols next to them or discussed in the text.



### **ELECTRIC SHOCK**

Touching electrical components can cause fatal electric shock and severe burns. By using a dry insulating mat or cover, insulate yourself from the workpiece and ground. While the machine is

powered on, do not remove the machine cover, or touch any electrical components or circuits without a pair of proper and dry insulating gloves. Equipment that has been incorrectly placed or grounded is a hazard. ELECTRIC SHOCK can cause death or severe injuries. Do not touch any active electrical components. Wear dry insulating gloves and body protection with no holes in them. Use dry insulating mats or blankets large enough to avoid any direct touch with the work or ground to isolate oneself from the work and ground. If the torch pieces touch the work or the ground, do not touch them. Inspect the input power cable and ground conductor on a regular basis for aging or bare wiring; repair promptly if damaged; bare wiring can kill. When not in use, turn off all equipment. Do not utilize cables that are worn, broken, undersized, or repaired. Avoid wrapping the torch cable around your body. If codes demand it, connect the workpiece to a good electrical (earth) ground. Only use well-maintained equipment. Repair or replace broken pieces at the same time. When operating above floor level, use a safety harness. Maintain the integrity of all panels and coverings. Do not try to bypass or overcome the safety mechanisms. Only use the torch types which indicated in the owner's manual. When the trigger is pressed, keep your hands away from the electrode/tungsten tip and the arc. Clamp the work cable to the workpiece (not a component that will fall away) or the worktable as close to the welding area as possible. When not attached to the workpiece, insulate the work clamp to avoid contact with any metal objects. Before inspecting, cleaning, or replacing torch parts, and before installing or repairing this machine, turn off the power. Install, ground, and operate this equipment in accordance with its owner's manual and any national, province, state, and local laws. Always ensure that the input power cord ground wire is correctly connected to the ground terminal and the cord connector is attached to a properly grounded receptacle outlet. Attach the correct grounding conductor first while establishing input connections. Maintain cables by keeping them dry, clear of oil and grease, and away from hot metal and sparks.



**High DC VOLTAGE exists inside the machine even after turning off.**

Even after disconnecting the input power, there is dangerous DC voltage in inverter welding power sources. Before touching any parts, turn off the inverter, disconnect the input power, and wait for the input capacitors to discharge.



**BURNS AND ELECTRIC SHOCK RISK WEAR DRY INSULATED GLOVES.**

When replacing the consumables, always use dry insulated gloves. During welding, the consumables get extremely hot, and serious burns are possible. If the power supply is turned on, touching the consumables might cause an electric shock. Never touch the exposed parts of the welding torch/electrode holder of the machine, change or clean consumables while the machine is on, because the shocking

voltage between the parts will be extremely dangerous and even fatal.



#### **WELDING can result in a fire or explosion.**

From the welding arc, hot metal and sparks are ejected that can cause fire or explosion. Before performing any welding, double-check that the location is safe. Welding has the potential to start a fire or explosion. Remove all combustible materials around the work area. If this isn't feasible, use certified covers to firmly cover them. Avoid welding in areas where flying sparks might ignite combustible materials. Make sure you and others are safe from flying sparks and hot metal. Be aware that welding sparks and hot materials can easily pass-through minor gaps and holes and onto surrounding places. Keep an eye out for flames and a fire extinguisher nearby. Welding on a ceiling, floor, bulkhead, or wall might result in a fire on the concealed side. Do not weld on combustible-filled containers or closed containers like tanks, drums, or pipelines unless they have been adequately prepared according to relevant safety standards. Check the area for sparks, glowing embers, and flames when the task is completed. Only use the proper fuses or circuit breakers. Do not oversize or bypass them. All work should be done in accordance with applicable safety regulations, and a fire watcher and extinguisher should be available. To avoid welding currents from traveling too long, perhaps unknown courses and generating electric shock, sparks, and fire dangers, connect the work cable to the work as near to the welding area as possible. Never weld on containers containing potentially combustible products; they must first be emptied and thoroughly cleaned. Never perform welding where combustible dust, gas, or liquid vapors (such as gasoline) are present in the atmosphere. Welding pressurized cylinders, pipelines, or containers is prohibited. Wear flame-resistant, long-lasting body protection (leather, heavy cotton, wool). Oil-free clothes, such as leather gloves, a thick shirt, cuffless pants, work boots with electrical insulated sole, and a hat, are all recommended for body protection. Avoid placing the device near or on flammable materials. Before performing any welding, make sure you don't have any combustibles on you, such as butane lighter or matches.



#### **EXCESSIVE NOISE HAZARD**

Be cautious if there is excessive noise in the workplace. Wear hearing protection if the noise level is too high. Workers nearby are also impacted by noise and may require hearing protection.



#### **Hot PARTS HAZARD**

All welded pieces become extremely hot immediately after welding or cutting, causing burns to anybody in touch with exposed skin. After welding or cutting, do not contact the workpiece, ground clamp, or electrode holder/torch instantly, and wait for a cooling interval before picking them up. To avoid burns, use proper equipment while working with hot parts, and use thick insulating welding/cutting gloves and clothes as well.



#### **WELDING/CUTTING FUMES HAZARD**

Welding and cutting generate gases and fumes. The inhalation of these gases and vapors might be hazardous. These gases and fumes can replace

oxygen in the body, causing harm or death. Keep your head away from the welding or cutting area and avoid inhaling the fumes and gases. If the weld/cut is indoors, ventilate the environment or utilize local forced ventilation at the weld site to eliminate smoke and gas. Wear an authorized air supply respirator if ventilation is insufficient. Only work inside if you are properly ventilated or using an air-supplied respirator. For any materials being used, read the Material Safety Data Sheet (MSDS) and the manufacturer's instructions.



#### **DANGEROUS GASES AND FUMES HAZARD**

Welding and cutting coated metal, such as stainless steel, are not permitted, unless the coating has been removed from the weld or cut area, and the area is thoroughly ventilated, and an air-supplied respirator is used as well. During welding or cutting, the coating and all metals containing these elements can produce harmful fumes. Do not cut containers that contain poisonous or reactive products or containers that have previously held toxic or reactive materials; they must first be emptied and thoroughly cleaned. Cut away from degreasing, cleaning, or spraying processes. The arc's heat and light can combine with vapors to produce very poisonous and unpleasant fumes.



#### **DANGEROUS GAS HAZARD FROM THE SHIELDING / CUTTING GAS CYLINDERS**

Turn off the shielding/cutting gas, when not in use. These gases can displace air, lowering oxygen levels and resulting in harm or death.



#### **CYLINDERS can explode if they are damaged.**

Excessive heat, mechanical shocks, physical damage, slag, open flame, sparks, and arcs should all be avoided while using compressed gas cylinders. Keep cylinders away from any electrical or cutting/welding circuits. Never allow a welding torch/electrode holder or plasma arc torch to make electrical contact with a cylinder. An explosion will occur if you cut a pressurized cylinder. When the cylinder is not in use or attached for use, keep the protective cap on the valve. To avoid falling or tipping, install and secure cylinders in an upright position by chaining them to a fixed support or equipment cylinder rack. Lift and move cylinders with the proper equipment, procedures, and a sufficient number of people. Read and obey the directions on compressed gas cylinders, associated equipment, and Compressed Gas Association (CGA). Use just the right compressed gas cylinders, regulators, hoses, and fittings for the job, and keep them and their parts in excellent working order. When opening the cylinder valve, face away from the valve outlet. When opening the valve, make sure you're not standing in front of or behind the regulator.



#### **WELDING/CUTTING RAYS HAZARD**

The visible and invisible light (ultraviolet and infrared rays) produced by the welding or cutting process can burn the eyes and skin. Wear an appropriate welding helmet with suitably shaded filter lenses to protect your face and eyes from welding rays. Cover any exposed skin, arms, or neck. Wear protective clothing made of flame-resistant material (leather, thick cotton, or wool). Protect people from flashes, glare, and sparks by using a safety screen or barriers.





### ESD- ELECTROSTATIC DISCHARGE

During welding/cutting, an electric static charge can be produced and released into any items contacted by the welder/cutter after welding/cutting. Before touching any boards or electronic components, put on a grounded wrist strap. When storing, moving, or shipping PC boards, use proper static-proof bags and boxes.



### MOVING PARTS HAZARD

Typical welding/cutting machines may include several moving elements, such as rollers and fans. Hands should be kept away from moving elements like fans. Keep a safe distance from moving parts.

Keep your distance from pinch spots like drive rolls. Keep loose garments and hair out of the path of moving parts. All doors, panels, covers, and guards should be closed and secured. Only allow qualified individuals to remove doors, panels, coverings, or guards as needed for maintenance and troubleshooting. When the maintenance is performed, reinstall the doors, panels, covers, or guards before reconnecting the input power.



### BATTERY EXPLOSION can cause injury.

Do not use welding machine to charge batteries or jump start vehicles that can cause explosion.



### FALLING EQUIPMENT can cause injury.

Lift just the unit, not the gas cylinders, or other attachments together. Make sure you have equipment with adequate capacity to raise the unit.

If you're going to relocate the unit using lift forks, be sure they're long enough to reach the other side. When working from an aerial location, keep equipment (cables and cords) out of the way of moving vehicles.



### Sparks and hot metal blow out from the cutting arc can cause injury.

Flying hot metal generated by chopping and grinding can cause injury. Wear a face shield or safety goggles with side shields that are approved.

Protect your skin by wearing suitable body protection. To prevent sparks from entering your ears, use flame-resistant ear plugs or earmuffs. Wear safety glasses with side shields or wear face shields.



### EXPLODING INVERTER PARTS can cause injury.

When electricity is connected to inverter power sources, faulty parts can explode or cause other parts to explode. Turn off the power source and then start to service the inverters, and always wear a face shield and long sleeves to protect your body and skin.



### EMF- ELECTRIC MAGNETIC FIELDS can cause fault in electrical devices such as pacemakers.

Electric magnetic fields are formed during welding or cutting, which might cause faults in electrical components or Implanted Medical Devices in the surrounding area. Those who wear pacemakers or other implanted medical devices should stay away from EMF emitted by welders/cutters. Before arc welding, spot welding, gouging, plasma arc cutting, or induction heating operations, wearers of

implanted medical devices should consult their doctor and the device manufacturer.



### Welding can cause interference in electronic equipment.

Electronic equipment, such as computers and computer-driven equipment, such as robots, can be harmed by electromagnetic energy. Keep

cables short, close together, and low as possible, to prevent any interference. Welding should be done far away from any sensitive electrical equipment. Ensure that this welding power source is installed and grounded in accordance with the instructions in this manual. If interference still occurs, the user should consider relocating the equipment, employing shielded cables, utilizing line filters, or shielding the workspace.




### Moving PARTS can bring injury

Avoid touching moving components.  
Avoid tight spots, such as drive rolls.



### Welding wire has the potential to cause harm

Wait to pull the trigger on the gun until directed to. When threading welding wire, never point a gun at the human body, any metal, or any other object.



### ELECTRIC SHOCK RISK

Keep your hands and other metallic items far from the welding wire and driving components while the procedure is in progress.

## 1.3 Important Safety Precautions

- Put on dry insulating gloves. Avoid touching the electrode with your bare hand. Wearing damp or damaged gloves is not permitted.
- Injuries can be caused by flying components. When servicing a unit, always wear a face shield. Put on a cap and safety glasses. Wear a welding helmet with the appropriate filter shade. Wear full bodily protection.
- The most unstable position of the equipment must not be inclined up more than 10°. Auxiliary components such as gas cylinders, wire feed units, or cooling devices may impact stability depending on the kind of equipment, and they must be considered.
- Before changing torch consumables, working on the machine, turn off the power and unplug the input plug.
- After the power is switched off, dangerous voltage remains on the input capacitors. Do not touch fully charged capacitors. Always wait 60 seconds after turning off the power before working on the machine and check the input capacitor voltage to ensure it is near zero before touching any parts.

## 1.4 Minimizing EMF (Electrical and Magnetic Fields) Exposure from the Welding / Cutting Circuit.

Arc welding and related processes such as gouge, plasma arc cutting, and spot welding generate an EMF field surrounding the welding circuits. Some medical devices, such as pacemakers, can be affected by EMF. Protective precautions for those who have medical implants must be implemented. For example, limit passing by or do individual risk assessments for welders. By following the relevant procedures, EMF exposure can be

reduced. Twist or tape cables together, or use a cable cover, to keep them close together.

**Precautions about Implanted Medical Devices:** Before performing or going near arc welding, spot welding, gouging, plasma arc cutting, or induction heating procedures, implanted medical device wearers should consult their doctor and the device manufacturer. Follow the above procedures only if your doctor has approved you. Avoid putting your body between welding or cutting cables. Arrange the wires so that they are to one side and away from the operator. Work away from the welding power source and do not sit or lean on it. Keep your head and body as far away from the welding circuit's equipment as possible. Work clamp should be connected to the workpiece as near to the weld or cut area as possible. Welding should not be done while carrying the welding or cutting power source or wire feeder. If you have an Implanted Medical Device in your body, you should consult your doctor before doing or going near arc welding, spot welding, gouging, or plasma arc cutting activities. Do not wrap cables around your body or coil them. It is the user's responsibility to install and operate the equipment in accordance with the manufacturer's instructions. If electromagnetic disturbances are detected, it is the user's obligation to fix the problem with the manufacturer's technical help. In other circumstances, resolving the problem may be easy by connecting the machine to the earth and the workpiece. In other circumstances, it might include building an electromagnetic screen that encloses the power source and the work area, along with applying some input filters. Cutting/welding equipment must be connected to the power source in accordance with the manufacturer's instructions. If interference occurs, further precautions, such as mains supply filtering, may be required. Shielding the supply cable of permanently installed equipment in metallic conduit or equivalent should be considered. The shielding should be electrically continuous over its whole length. The shielding should be attached to the power supply to preserve excellent electrical contact between the conduit and the power source enclosure. The user must analyze any electromagnetic concerns in the surrounding region before installing the device. The user must confirm that all other devices in the area are compatible. This may necessitate extra precautions. Where the workpiece is not tied to earth for electrical safety or because of its size and location, such as a ship's hull or constructing steel work, a connection linking the workpiece to earth may minimize emissions in some cases. The workpiece without earth increases the danger of harm to users or damage to other electrical equipment. The workpiece should be connected to earth by a direct connection to the workpiece. If direct connection is not permitted, bonding should be accomplished via adequate capacitances determined in accordance with national rules. Changing the earth circuit arrangements should be authorized only by someone who is qualified to assess whether the alterations would raise the danger of injury, such as by enabling parallel cutting/welding current return pathways, which may damage the earth circuits of other equipment. IEC 60974-9 provides additional advice, Arc Welding Equipment, Part 9: Installation and Use.

Interference concerns may be alleviated by selective screening and shielding of other cables and equipment in the direct vicinity. For some particular applications, screening of the complete cutting/welding system may be considered.

### **1.5 Grounding of Welding/Cutting Machines:**

In an electric circuit, there is an active wire that supplies power, a neutral wire that returns the current and a 'grounding wire' that provides an additional path for electrical current to safely return to the ground in the event of a short circuit. A copper conductor is connected from the wiring system's metal rod to a set of ground connection terminals in the service panel. Because electricity always seeks the shortest path to the earth, if the neutral wire is broken or interrupted, it is the grounding wire that provides a direct path to the ground. Because of this direct physical connection, the earth can act as the path of least resistance, preventing an appliance or person from becoming the shortest path.

#### **Importance of Electrical Grounding**

**Protects Against Electrical Overloads:** You may occasionally experience power surges or be struck by lightning during severe weather conditions. These occurrences may generate dangerously high levels of electricity, which can destroy your electrical appliances. By grounding the electrical system, all excess electricity is directed to the earth rather than frying the system's connected appliances. The appliances will be secure and safe from large electrical surges.

**Stabilizes the Voltage Levels:** Grounding the electrical system makes it easier to distribute the right amount of power to the right places. This ensures that the circuits are never overloaded and, as a result, do not blow. The earth can be regarded as a common reference point for any electrical system's voltage sources. This aids in maintaining stable voltage levels throughout the electrical system.

**Earth Conducts with Least Resistance:** One of the primary reasons for grounding your electrical appliances is that the earth is a great conductor, capable of carrying all excess electricity with minimal resistance. When you ground the electrical system and connect it to the earth, you are allowing excess electricity to flow somewhere without resistance rather than through you or your appliances.

**Prevents Serious Damage and Death:** When you fail to ground the electrical system, you endanger your appliances and even your life. When high voltage is passed through a device, it is fried and irreparably damaged. An excess of electricity can even start a fire, endangering your property and the lives of your loved ones.

**Welding and Cutting Equipment Grounding:** Welding/cutting machines are typically grounded via a third grounding wire connected to their electrical connections. Mobile engine-driven generator welding units should be grounded by connecting a cable from the machine's ground stud to a metal stake driven into the ground. Always follow the manufacturer's instructions for properly grounding the model being used. Auxiliary receptacles on welding machines may or may not be protected by a ground-fault circuit interrupter (GFCI). In wet or damp areas, GFCI adapters or "pigtailed" should be used. Tools, extension cords, and other items plugged into these receptacles must be

grounded or double insulated. When connecting the work piece to the welding table, make sure the table is grounded as well (typically a cable from the table leg to the building structure). Avoid grounding to a structure that is a long distance away from the weld. Never use flammable liquid pipelines as a ground, and never use electrical conduit as a ground.

**Precautions to prevent an electrical shock:** To reduce the extent of live parts, ensure that all cables are in good condition, with no bare insulation or frayed wires. Keep cables safe from vehicle traffic and other hazards so they don't get damaged, cut, or pinched. Check that the rod electrode holder is properly insulated. During a welding/cutting operation, always keep your hands and body dry. Avoid standing in water, on wet surfaces, using wet hands, or wearing sweaty clothing. Never immerse energized (hot) electrode holders or torches in water. Avoid coming into direct contact with live welding equipment and the workpiece. Connect the work or metal to a good electrical ground. Always shield yourself from the work and the ground. If performing arc welding in wet or high humidity conditions, wear appropriate protective equipment such as rubber boots and rubber pads. Wear rubber gloves beneath your welding gloves. Use an insulating mat under the operator if the welding/cutting operation must be performed on steel or another conductive material. Put the welding or cutting machine in close proximity. In the event of an emergency or an accident, the machine can be quickly turned off to cut off the power source. When not in use or on breaks, turn off the welding or cutting machine. Before leaving the cutting/welding area, disconnect the machine from the power grid. When moving from one working position to another, do not hold or move the torch/electrode holder and the Ground (Earth) return cable at the same time. If the power source to the equipment has not been cut.

#### **What should I do in case of an electric shock?**

Call for medical assistance right away. **DO NOT USE YOUR "BARE HANDS"** on the victim until he or she is away from the live electrical source. If an appliance or electrical equipment is the electrical source, turn off the power at the fuse box or circuit breaker panel, or, if possible, turn off the appliance or electrical equipment and unplug it. Simply turning off the equipment is insufficient. If the electricity cannot be turned off and the victim is still in contact with the electrical source, determine whether the victim should be moved, or the wire should be pushed away from the victim (call for emergency help if the wire is a high voltage power line). Wear dry gloves or cover your hands with cloth if you must move a victim away from a live contact, and stand on dry insulating material such as cardboard, wood, or clothes. When attempting to move the victim, ensure that you have good footing and will not slip or fall. Move the wire or power source away from the victim or push the victim off the live electrical source with a dry piece of wood, broom, or other dry, insulating object or material. If there is a risk of neck or spinal injuries (for example, from a fall), do not move the victim unless absolutely necessary. If the victim is not breathing, provide artificial respiration. If the victim's heart has stopped, perform CPR (only if you are trained in CPR). Apply a sterile dressing to burns. There could be burns where the power source touched the victim and where the electricity exited the body (to ground). Electrical burns may

appear minor on the surface, but they can be severe deep within the tissue. Maintain the victim's comfort, warmth, and rest, and keep an eye on his or her breathing.

#### **Information Sources for Grounding**

American Welding Society, ANSI Z49.1:2005 "Safety in Welding, Cutting & Allied Processes."

National Fire Protection Association, NFPA 70, "National Electrical Code", 2005.

American Welding Society, Safety and Health Fact Sheet No. 29, "Grounding of Portable and Vehicle Mounted Welding Generators", July 2004.

American Welding Society, AWS A3.0-2001, "Standard Welding Terms and Definitions"

#### **Guide for Helmet Shade Number**

When cutting or watching, use face protection (helmet or shield) with appropriate filter glasses to protect your face and eyes from arc rays and sparks (see Safety Standards). The suggested colors in the table below are offered for the convenience of the operator.

Process	Welding Current (A)	Minimum Protective Shade Size	Recommended* Shade Size
GMAW / MIG & Flux Cored Arc Welding (FCAW)	Less than 55	7	-
	55 to 155	10	11
	155 to 240	10	12
Gas Tungsten Arc Welding (GTAW)	Less than 50	8	10
	50 to 150	8	12
	150 to 500	10	14
Shielded Metal Arc Welding (SMAW)	Less than 60	7	10
	60 to 160	8	10
	160 to 250	10	12
	250 to 550	11	14
<b>Recommendation:</b> take a shade that is too dark to see the weld zone. Then try a lighter shade which ensures sufficient view of the weld zone without going below the minimum.			

#### **Additional Safety Information**

**Safety in Welding, Cutting, and Allied Processes**, CSA Standard W117.2 from Canadian Standards Association. Website: [www.csagroup.org](http://www.csagroup.org)

**OSHA Occupational Safety and Health Standards for General Industry**, Title 29, Code of Federal Regulations (CFR), Part 1910.177 Subpart N, Part 1910 Subpart Q, and Part 1926, Subpart J. Website: [www.osha.gov](http://www.osha.gov)

**OSHA Important Note Regarding the ACGIH TLV, Policy Statement** on the Uses of TLVs and BEIs. Website: [www.osha.gov](http://www.osha.gov).

**Applications Manual for the Revised NIOSH Lifting Equation** from the National Institute for Occupational Safety and Health (NIOSH). Website: [www.cdc.gov/niosh](http://www.cdc.gov/niosh).

**Standard for Fire Prevention During Welding, Cutting, and Other Hot Work**,

NFPA Standard 51B from National Fire Protection Association. Website: [www.nfpa.org](http://www.nfpa.org).

**Safety in Welding, Cutting, and Allied Processes**, American Welding Society standard ANSI Standard Z49.1. Website: [www.aws.org](http://www.aws.org).

**Safe Handling of Compressed Gases in Cylinders**, CGA Pamphlet P-1 from Compressed Gas Association. Website:



**Safe Practices for Welding and Cutting Containers that have Held Combustibles**, American Welding Society Standard AWS A6.0 from Global Engineering Documents. Website: [www.global.ihc.com](http://www.global.ihc.com).

**Safe Practices for the Preparation of Containers and Piping for Welding and Cutting**, American Welding Society Standard AWS F4.1 from Global Engineering Documents.

Website: [www.global.ihc.com](http://www.global.ihc.com).

**Safe Practice for Occupational and Educational Eye and Face Protection**, ANSI Standard Z87.1 from American National Standards Institute. Website: [www.ansi.org](http://www.ansi.org).

## ⚠Précautions de sécurité et les symboles (French)

### Mesures de sécurité generals

Les utilisateurs d'équipement de soudage et de découpe au plasma Canaweld sont en fin de compte responsables de s'assurer que toute personne travaillant sur ou autour de l'équipement respecte toutes les mesures de sécurité. Les mesures de sécurité doivent répondre aux critères d'un équipement de soudage ou de découpe au plasma de ce type. En plus des lois habituelles sur le lieu de travail, les directives suivantes doivent être suivies. Pour assurer votre sécurité et celle des autres, lisez, respectez et conservez ces avertissements de sécurité et instructions d'utilisation essentiels. Vous êtes entièrement responsable de l'utilisation sûre du produit. Canaweld ne donne et ne peut donner aucune assurance ou garantie quant à la sécurité du produit dans votre environnement. Cet appareil n'est pas conçu pour être utilisé dans des zones résidentielles où l'alimentation électrique provient d'une source publique de basse tension. En raison des perturbations conduites et rayonnées, il peut être difficile d'assurer la compatibilité électromagnétique de l'appareil dans certaines régions. Ce produit est uniquement destiné à enlever du métal. Toute autre utilisation peut entraîner des blessures corporelles et/ou endommager l'équipement. En cas de dysfonctionnement, contactez un professionnel pour obtenir de l'aide. Tous les travaux doivent être effectués par des employés qualifiés qui connaissent le fonctionnement de l'équipement de soudage ou de découpe au plasma. Une utilisation incorrecte de l'équipement peut conduire à des circonstances dangereuses, entraînant des blessures pour l'opérateur et des dommages pour l'équipement. Toute personne qui travaille avec un équipement de soudage ou de découpe au plasma doit comprendre comment il fonctionne, où se trouvent les arrêts d'urgence, quelles sont les mesures de sécurité à respecter et comment utiliser la découpe au plasma et/ou le soudage. Utilisez des équipements de sécurité personnelle approuvés, tels que des lunettes de sécurité, des vêtements résistant aux flammes et des gants de sécurité. Évitez de porter des écharpes, des bracelets, des bagues et d'autres articles amples qui pourraient se coincer ou causer des brûlures. L'opérateur doit garantir qu'aucune personne non autorisée ne se trouve dans la zone de travail de l'équipement lorsqu'il est allumé et que personne n'est exposé à l'arc lorsqu'il est amorcé. L'environnement de travail doit être

exempt de courants d'air et adapté à la tâche. Le câble de retour doit être solidement connecté et les travaux sur les équipements à haute tension ne doivent être effectués que par un électricien qualifié. Un équipement d'extinction d'incendie approprié et clairement identifié doit être à portée de main. Pendant que l'équipement est en fonctionnement, ne le lubrifiez pas et ne l'entretenez pas.



### Précautions et symboles de sécurité

#### Avant de travailler sur la machine, lisez le manuel d'utilisation.

Lisez les informations de sécurité au début du manuel. Trouvez chaque partie à étudier dans le manuel pour bien comprendre les capacités de la machine. Respectez les manuels du propriétaire, les normes industrielles et les exigences nationales, provinciales, étatiques et locales.



#### DANGER!

Le symbole indique une action dangereuse qui entraînera la mort ou des blessures graves si elle n'est pas évitée. Les dangers ou risques potentiels sont représentés par les symboles qui leur sont accolés ou discutés dans le texte.



#### CHOC ELECTRIQUE

Le contact avec des composants électriques peut provoquer un choc électrique mortel et des brûlures graves. En utilisant un tapis isolant sec ou une couverture, isolez-vous de la pièce à travailler et de la terre. Lorsque la machine est sous tension, ne retirez pas le capot de la machine et ne touchez pas les composants ou circuits électriques sans un gant isolant sec et approprié. Un équipement mal placé ou mal mis à la terre présente un risque. Les CHOCS ELECTRIQUES peuvent causer la mort ou des blessures graves. Ne pas entrer en contact avec des composants électriques actifs. Porter des gants isolants secs et des protections corporelles non trouées. Utiliser des tapis ou des couvertures isolants secs suffisamment grands pour éviter tout contact direct avec l'ouvrage ou le sol afin de s'isoler de l'ouvrage et du sol. Si les pièces de la torche entrent en contact avec l'ouvrage ou le sol, ne pas les toucher. Inspectez régulièrement le câble d'alimentation d'entrée et le conducteur de terre pour vérifier qu'ils ne sont pas vieillissants ou dénudés ; réparez-les rapidement s'ils sont endommagés ; les fils dénudés peuvent tuer. Lorsque vous n'utilisez pas l'appareil, éteindre tous les équipements. N'utilisez pas de câbles usés, cassés, sous-dimensionnés ou réparés. Évitez d'enrouler le câble du chalumeau autour de votre corps. Si les codes l'exigent, connectez la pièce de travail à une bonne mise à la terre électrique (earth). N'utilisez que du matériel bien entretenu. Réparez ou remplacez les pièces cassées en même temps. Lorsque vous travaillez au-dessus du niveau du sol, utilisez un harnais de sécurité. Maintenez l'intégrité de tous les panneaux et revêtements. N'essayez pas de contourner ou de surmonter les mécanismes de sécurité. N'utilisez que les types de torche indiqués dans le manuel d'utilisation. Lorsque vous appuyez sur la gâchette, gardez vos mains de l'électrode/du bout du tungstène et de l'arc. Fixez le câble de travail à la pièce (et non à un élément qui va tomber) ou à la table de travail, aussi près que possible de la zone de soudage. Lorsqu'elle n'est pas fixée

à la pièce, isolez la pince de travail pour éviter tout contact avec des objets métalliques. Avant d'inspecter, de nettoyer ou de remplacer des pièces de la torche, et avant d'installer ou de réparer cette machine, mettez-la hors tension. Installez, mettez à la terre et utilisez cet équipement conformément au manuel d'utilisation et aux lois nationales, provinciales, nationales et locales. Assurez-vous toujours que le fil de terre du cordon d'alimentation d'entrée est correctement connecté à la borne de terre et que le connecteur du cordon est fixé à une prise de courant correctement mise à la terre. Fixez d'abord le bon conducteur de mise à la terre lorsque vous établissez les connexions d'entrée. Entretenez les câbles en les gardant au sec, exempts d'huile et de graisse, et à l'écart du métal chaud et des étincelles.



**Une tension continue élevée existe à l'intérieur de la machine même après l'avoir éteinte.**

Même après avoir déconnecté l'alimentation d'entrée, il existe une tension continue dangereuse dans les sources d'alimentation de soudage de

l'onduleur. Avant de toucher une quelconque pièce, éteignez l'onduleur, déconnectez l'alimentation d'entrée et attendez que les condensateurs d'entrée se déchargent.



**RISQUE DE BRÛLURES ET DE CHOC ÉLECTRIQUES - PORTER DES GANTS SECS ISOLÉS**

Lors du remplacement des consommables, utilisez toujours des gants secs et isolés. Pendant le soudage, les consommables deviennent extrêmement chauds et des brûlures graves sont possibles. Si l'alimentation électrique est sous tension, le fait de toucher les consommables peut provoquer un choc électrique. Ne touchez jamais les parties exposées de la torche de soudage/du porte-électrode de la machine, ne changez pas ou ne nettoyez pas les consommables lorsque la machine est allumée, car la tension de choc entre les pièces sera extrêmement dangereuse, voire mortelle.



**La soudure peut provoquer un incendie ou une explosion.**

L'arc de soudage projette du métal chaud et des étincelles qui peuvent provoquer un incendie ou une explosion. Avant d'effectuer toute soudure, vérifiez que l'endroit est sûr. Le soudage est susceptible de déclencher un incendie ou une explosion. Retirez tous les matériaux combustibles autour de la zone de travail. Si cela n'est pas possible, utilisez des couvertures certifiées pour les recouvrir fermement. Évitez de souder dans des zones où des étincelles pourraient enflammer des matériaux combustibles. Assurez-vous que vous et les autres personnes êtes à l'abri des étincelles et du métal chaud. Sachez que les étincelles de soudage et les matériaux chauds peuvent facilement passer à travers de petits trous et interstices et atteindre les endroits environnants. Gardez un œil sur les flammes et un extincteur à proximité. Le soudage sur un plafond, un plancher, une cloison ou un mur peut provoquer un incendie sur le côté caché. Ne soudez pas sur des récipients remplis de combustible ou des récipients fermés tels que des réservoirs, des fûts ou des canalisations, à moins qu'ils n'aient été préparés de manière adéquate conformément aux normes de sécurité en vigueur. Une fois la tâche terminée,

vérifiez l'absence d'étincelles, de braises incandescentes et de flammes dans la zone. N'utilisez que les fusibles ou les disjoncteurs appropriés. Ne les surdimensionnez pas et ne les contournez pas. Tous les travaux doivent être effectués conformément aux règles de sécurité en vigueur, et un surveillant d'incendie et un extincteur doivent être disponibles. Pour éviter que les courants de soudage ne se déplacent trop longtemps, peut-être sur des parcours inconnus, et ne génèrent des chocs électriques, des étincelles et des risques d'incendie, connectez le câble de travail à l'ouvrage aussi près que possible de la zone de soudage. Ne soudez jamais sur des récipients contenant des produits potentiellement combustibles; ils doivent d'abord être vidés et soigneusement nettoyés. Ne jamais effectuer de soudage lorsque des poussières, des gaz ou des vapeurs liquides combustibles (comme l'essence) sont présents dans l'atmosphère. Il est interdit de souder des bouteilles, des canalisations ou des conteneurs sous pression. Portez des protections corporelles résistantes aux flammes et de longue durée (cuir, coton lourd, laine). Pour la protection corporelle, il est recommandé de porter des vêtements exempts d'huile, tels que des gants en cuir, une chemise épaisse, un pantalon sans revers, des bottes de travail avec une semelle isolée électriquement et un chapeau.

Évitez de placer l'appareil à proximité ou sur des matériaux inflammables. Avant d'effectuer des travaux de soudage, assurez-vous que vous n'avez pas de combustibles sur vous, comme un briquet au butane ou des allumettes.



**RISQUE DE BRUIT EXCESSIF**

Soyez prudent s'il y a un bruit excessif sur le lieu de travail. Portez des protections auditives si le niveau sonore est trop élevé. Les travailleurs à proximité sont également touchés par le bruit et peuvent avoir besoin de protections auditives.



**DANGER LIÉ AUX PIÈCES CHAUDES**

Toutes les pièces soudées deviennent extrêmement chaudes immédiatement après le soudage ou le coupage, provoquant des brûlures à toute personne en contact avec la peau exposée. Après le soudage ou le coupage, ne pas toucher instantanément la pièce, la pince de masse ou le porte-électrode/la torche, et attendre un intervalle de refroidissement avant de les ramasser. Pour éviter les brûlures, utilisez un équipement approprié lorsque vous travaillez avec des pièces chaudes, ainsi que des gants et des chiffons de soudage/coupage épais et isolants.



**RISQUE DE FUMÉES DE SOUDAGE/COUPAGE**

Le soudage et le coupage génèrent des gaz et des fumées. L'inhalation de ces gaz et vapeurs peut être dangereuse. Ces gaz et vapeurs peuvent remplacer l'oxygène dans le corps, ce qui peut causer des dommages ou la mort. Tenez votre tête éloignée de la zone de soudage ou de découpage et évitez d'inhaler les fumées et les gaz. Si la soudure/le découpage a lieu à l'intérieur, ventilez l'environnement ou utilisez une ventilation forcée locale sur le site de soudure pour éliminer la fumée et les gaz. Porter un appareil respiratoire à adduction d'air autorisé si la ventilation est insuffisante. Ne travaillez à l'intérieur que si vous êtes correctement ventilé ou si vous utilisez un respirateur à

adduction d'air. Pour tous les matériaux utilisés, lisez la fiche de données de sécurité (FDS) et les instructions du fabricant.



### **RISQUE DE GAZ ET DE FUMÉES DANGEREUX**

Le soudage et le coupage de métaux revêtus, comme l'acier inoxydable, ne sont pas autorisés, à moins que le revêtement n'ait été retiré de la zone de soudage ou de coupage, et que la zone soit bien ventilée et qu'un masque respiratoire à adduction d'air soit également utilisé. Pendant le soudage ou le découpage, le revêtement et tous les métaux contenant ces éléments peuvent produire des fumées nocives. Ne coupez pas les récipients qui contiennent des produits toxiques ou réactifs ou les récipients qui ont précédemment contenu des matériaux toxiques ou réactifs ; ils doivent d'abord être vidés et soigneusement nettoyés. Coupez à l'écart des processus de dégraissage, de nettoyage ou de pulvérisation. La chaleur et la lumière de l'arc peuvent se combiner aux vapeurs et produire des fumées très toxiques et désagréables.



### **DANGER DE GAZ DANGEREUX PROVENANT DES CYLINDRES DE GAZ DE BLINDAGE / DE COUPE**

Éteignez le gaz de protection/de coupe lorsqu'il n'est pas utilisé, car ces gaz peuvent déplacer l'air, abaisser les niveaux d'oxygène et entraîner des blessures ou la mort.



### **RISQUE DE RAYONS DE SOUDAGE/ COUPAGE**

La lumière visible et invisible (rayons ultraviolets et infrarouges) produite par le processus de soudage ou de coupage peut brûler les yeux et la peau.

Portez un casque de soudage approprié avec des lentilles filtrantes convenablement ombragées pour protéger votre visage et vos yeux des rayons de soudage. Couvrez toute peau, bras ou cou exposés. Portez des vêtements de protection fabriqués dans un matériau résistant aux flammes (cuir, coton épais ou laine). Protégez les personnes contre les éclairs, l'éblouissement et les étincelles en utilisant un écran ou des barrières de sécurité.



### **Les CYLINDRES peuvent exploser s'ils sont endommagés.**

La chaleur excessive, les chocs mécaniques, les dommages physiques, les scories, les flammes nues, les étincelles et les arcs électriques doivent être évités lors de l'utilisation des bouteilles de gaz comprimé.

Tenir les bouteilles à l'écart de tout circuit électrique ou de tout circuit de coupure ou de soudage. Ne laissez jamais une torche de soudage/un porte-électrode ou une torche à arc plasma entrer en contact électrique avec une bouteille. Une explosion se produira si vous coupez une bouteille sous pression. Lorsque la bouteille n'est pas utilisée ou fixée pour être utilisée, gardez le bouchon de protection sur le robinet. Pour éviter de tomber ou de basculer, installez et fixez les bouteilles en position verticale en les enchaînant à un support fixe ou à un support de bouteilles d'équipement. Soulevez et déplacez les bouteilles avec l'équipement et les procédures appropriés et un nombre suffisant de personnes. Lisez et respectez les instructions figurant sur les bouteilles de gaz comprimé, l'équipement associé et la Compressed Gas Association (CGA). Utilisez les bouteilles de

gaz comprimé, les détendeurs, les tuyaux et les raccords qui conviennent le mieux à votre travail et maintenez-les, ainsi que leurs pièces, en excellent état de fonctionnement. Lorsque vous ouvrez le robinet de la bouteille, ne vous approchez pas de la sortie du robinet. Lorsque vous ouvrez le robinet, assurez-vous de ne pas vous tenir devant ou derrière le détendeur.



### **ESD-DÉCHARGE STATIQUE ELECTRIQUE**

Pendant le soudage/la découpe, une charge électrique statique peut être produite et libérée dans tous les objets avec lesquels le soudeur/la découpe entre en contact après le soudage/la

découpe. Avant de toucher des cartes ou des composants électroniques, mettez un bracelet relié à la terre. Lorsque vous stockez, déplacez ou expédiez des cartes PC, utilisez des sacs et des boîtes antistatiques appropriés.



### **RISQUE D'EXPOSITION À DES PIÈCES EN MOUVEMENT**

Les machines de soudage/coupage typiques peuvent comprendre plusieurs éléments mobiles, tels que des rouleaux et des ventilateurs. Les

mains doivent être tenues à l'écart des éléments mobiles comme les ventilateurs. Gardez une distance de sécurité avec les pièces en mouvement. Restez à distance des points de pincement comme les rouleaux d'entraînement. Gardez les vêtements amples et les cheveux hors de la trajectoire des pièces mobiles. Toutes les portes, panneaux, couvercles et protections doivent être fermés et sécurisés. Ne permettez qu'à des personnes qualifiées de retirer les portes, panneaux, couvercles et protections doivent être fermés et sécurisés. Ne permettez qu'à des personnes qualifiées de retirer les portes, panneaux, couvertures ou protections si nécessaire pour la maintenance et le dépannage. Une fois l'entretien effectué, réinstallez les portes, panneaux, couvertures ou protections avant de reconnecter l'alimentation d'entrée.



### **L'EXPLOSION DE LA BATTERIE peut causer des blessures.**

N'utilisez pas la machine à souder pour charger des batteries ou démarrer des véhicules, car cela pourrait provoquer une explosion.



### **LA CHUTE D'UN ÉQUIPEMENT peut causer des blessures**

Ne soulevez que l'unité, et non le train de roulement, les bouteilles de gaz ou autres accessoires, à l'aide de l'anneau de levage. Assurez-vous de disposer d'un équipement d'une capacité suffisante pour soulever l'unité. Si vous devez déplacer l'appareil à l'aide de fourches de levage, assurez-vous qu'elles sont suffisamment longues pour atteindre l'autre côté. Lorsque vous travaillez depuis un emplacement aérien, gardez l'équipement (câbles et cordons) hors de la trajectoire des véhicules en mouvement.



### **Les étincelles et les projections de métal chaud provenant de l'arc de coupe peuvent causer des blessures.**

Les projections de métal chaud générées par le hachage et le meulage peuvent causer des blessures. Portez un écran facial ou des lunettes de sécurité avec écrans latéraux homologués. Protégez votre peau en portant une protection



corporelle appropriée. Pour éviter que les étincelles ne pénètrent dans vos oreilles, utilisez des bouchons d'oreille ou des protège-oreilles résistant aux flammes. Portez des lunettes de sécurité avec des écrans latéraux ou des écrans faciaux.



### **L'EXPLOSION DES PIÈCES DE L'INVERSEUR peut provoquer des blessures.**

Lorsque l'électricité est connectée aux sources d'alimentation des onduleurs, les pièces défectueuses peuvent exploser ou provoquer l'explosion d'autres pièces. Coupez la source d'alimentation et commencez à entretenir les onduleurs, et portez toujours un écran facial et des manches longues pour protéger votre corps et votre peau.



### **Les champs électromagnétiques peuvent provoquer des défaillances dans les appareils électriques tels que les stimulateurs cardiaques.**

Des champs électromagnétiques se forment pendant le soudage ou le découpage, ce qui peut provoquer des défaillances dans les composants électriques ou les dispositifs médicaux implantés dans la zone environnante. Les personnes qui portent des stimulateurs cardiaques ou d'autres dispositifs médicaux implantés doivent rester à l'écart des CEM émis par les soudeurs/coupeurs. Avant toute opération de soudage à l'arc, de soudage par points, de gougeage, de découpe à l'arc plasma ou de chauffage par induction, les porteurs de dispositifs médicaux implantés doivent consulter leur médecin et le fabricant du dispositif.



### **La soudure peut provoquer des interférences dans les équipements électroniques**

Les équipements électroniques, tels que les ordinateurs et les équipements pilotés par ordinateur, comme les robots, peuvent être endommagés par l'énergie électromagnétique. Gardez les câbles courts, proches les uns des autres et aussi bas que possible, pour éviter toute interférence. Le soudage doit être effectué loin de tout équipement électrique sensible. Assurez-vous que cette source de courant de soudage est installée et mise à la terre conformément aux instructions de ce manuel. Si les interférences persistent, l'utilisateur doit envisager de déplacer l'équipement, d'utiliser des câbles blindés, des filtres de ligne ou de protéger l'espace de travail.




### **Les pièces en mouvement peuvent provoquer des blessures.**

Évitez de toucher les composants en mouvement. Évitez les endroits étroits, comme les rouleaux d'entraînement.



### **Le fil de soudure peut potentiellement causer des dommages**

Attendez d'avoir reçu l'ordre d'appuyer sur la gâchette du pistolet. Lorsque vous enfiler un fil de soudure, ne dirigez jamais le pistolet vers le corps humain, un métal ou tout autre objet.



### **RISQUE DE CHOC ÉLECTRIQUES**

Gardez vos mains et autres objets métalliques loin du fil de soudure et des composants d'entraînement pendant la procédure.

## **Mesures de sécurité importantes**

- Mettez des gants isolants secs. Évitez de toucher l'électrode à main nue. Le port de gants humides ou endommagés est interdit.
- Des blessures peuvent être causées par la projection de composants. Lors de l'entretien d'un appareil, portez toujours un écran facial. Mettez une casquette et des lunettes de sécurité. Portez un casque de soudage avec la teinte de filtre appropriée. Portez une protection corporelle complète.
- La position la plus instable de l'appareil ne doit pas être inclinée vers le haut de plus de 10°. Les composants auxiliaires tels que les bouteilles de gaz, les unités d'alimentation en fil ou les dispositifs de refroidissement peuvent avoir un impact sur la stabilité selon le type d'équipement, et il faut en tenir compte.
- Avant de changer les consommables de la torche, de travailler sur la machine, mettez-la hors tension et débranchez la fiche d'entrée.
- Après la mise hors tension, une tension dangereuse subsiste sur les condensateurs d'entrée. Ne pas entrer en contact avec des condensateurs complètement chargés. Attendez toujours 60 secondes après avoir coupé le courant avant de travailler sur la machine, et vérifiez que la tension du condensateur d'entrée est proche de zéro avant de toucher une quelconque pièce.

### **Minimiser l'exposition CEM (champs électriques et magnétiques) du circuit de soudage / coupage.**

Le soudage à l'arc et les procédés connexes tels que le découpage à la gouge, le découpage au plasma et le soudage par points génèrent un champ électromagnétique autour des circuits de soudage. Certains dispositifs médicaux, comme les stimulateurs cardiaques, peuvent être affectés par les CEM. Des précautions de protection doivent être prises pour les personnes qui ont des implants médicaux. Par exemple, il faut limiter le passage ou procéder à une évaluation individuelle des risques pour les soudeurs. En suivant les procédures appropriées, l'exposition aux CEM peut être réduite. Torsadez ou scotchez les câbles ensemble, ou utilisez un cache-câble, pour les maintenir proches les uns des autres.

### **Précautions concernant les dispositifs médicaux implantés:**

Avant d'effectuer ou de s'approcher de procédures de soudage à l'arc, de soudage par points, de gougeage, de découpe au plasma ou de chauffage par induction, les porteurs de dispositifs médicaux implantés doivent consulter leur médecin et le fabricant du dispositif. Ne suivez les procédures ci-dessus que si votre médecin vous a donné son accord. Évitez de mettre votre corps entre les câbles de soudage ou de coupe. Disposez les câbles de manière à ce qu'ils soient sur le côté et loin de l'opérateur. Travaillez loin de la source de courant de soudage et ne vous asseyez pas ou ne vous appuyez pas dessus. Gardez votre tête et votre corps aussi loin que possible de l'équipement du circuit de soudage. La pince de travail doit être reliée à la pièce à souder aussi près que possible de la zone de soudure ou de coupe. Le soudage ne doit pas être effectué en portant la source de courant de soudage ou de coupe ou le dévidoir de fil. Si vous avez un dispositif médical implanté dans votre corps,

vous devez consulter votre médecin avant d'effectuer ou de vous approcher d'activités de soudage à l'arc, de soudage par points, de gougeage ou de découpe à l'arc plasma. N'enroulez pas les câbles autour de votre corps et ne les enroulez pas. Il est de la responsabilité de l'utilisateur d'installer et d'utiliser l'équipement plasma conformément aux instructions du fabricant. Si des perturbations électromagnétiques sont détectées, il est de l'obligation de l'utilisateur de résoudre le problème avec l'aide technique du fabricant. Dans d'autres circonstances, il peut être facile de résoudre le problème en reliant la machine de découpe à la terre et à la pièce de travail. Dans d'autres circonstances, il peut s'agir de construire un écran électromagnétique qui entoure la source d'énergie et la zone de travail, ainsi que d'appliquer certains filtres d'entrée. Les équipements de coupe doivent être connectés à la source d'alimentation conformément aux instructions du fabricant. Si des interférences se produisent, des précautions supplémentaires, telles que le filtrage de l'alimentation secteur, peuvent être nécessaires. Le blindage du câble d'alimentation de l'équipement de coupe installé en permanence dans un conduit métallique ou équivalent doit être envisagé. Le blindage doit être électriquement continu sur toute sa longueur. Le blindage doit être fixé à l'alimentation électrique du matériel de coupe afin de préserver un excellent contact électrique entre le conduit et le boîtier de la source d'alimentation. L'utilisateur doit analyser tout préoccuper électromagnétique dans la région environnante avant d'installer l'appareil. L'utilisateur doit confirmer que tous les autres appareils de la région sont compatibles. Cela peut nécessiter des précautions supplémentaires. Lorsque la pièce de travail n'est pas reliée à la terre pour des raisons de sécurité électrique ou en raison de sa taille et de son emplacement, comme la coque d'un navire ou la construction d'un ouvrage en acier, une connexion reliant la pièce de travail à la terre peut minimiser les émissions dans certains cas. La pièce de travail sans mise à la terre augmente le risque de blessures pour les utilisateurs ou de dommages pour d'autres équipements électriques. La pièce de travail doit être reliée à la terre par une connexion directe à la pièce de travail. Si la connexion directe n'est pas autorisée, la mise à la terre doit être réalisée par des capacités adéquates déterminées conformément aux règles nationales. La modification des dispositions du circuit de terre ne doit être autorisée que par une personne qualifiée pour évaluer si les modifications augmentent le risque de blessure, par exemple en activation des voies de retour de courant de coupe parallèles, qui peuvent endommager les circuits de terre d'autres équipements. La norme CEI 60974-9 fournit des conseils supplémentaires, Matériel de soudage à l'arc, partie 9 : Installation et utilisation. Les problèmes d'interférence peuvent être atténués par le blindage sélectif d'autres câbles et équipements situés à proximité directe. Pour certaines applications, le blindage de l'ensemble du système de découpe au plasma peut être envisagé.

**1.6 Warning Label:** This power supply has this warning notice attached to it. It is critical that the operator and maintenance professional comprehend the meaning of these warning symbols.

These instructions, employer safety procedures, and material safety data sheets should all be read and followed. For complete understanding about safety in welding, cutting and allied processes, refer to CSA's W117.2:19 ([www.csagroup.org](http://www.csagroup.org)), OSHA's 29 CFR 1910 ([www.osha.gov](http://www.osha.gov)), American Welding Society's ANSI Z49.1:2021 ([www.aws.org](http://www.aws.org)) and ISO's 17846:2004 ([www.iso.org](http://www.iso.org)).

1 	1.1 	1.2 	1.3 
2 	2.1 	2.2 	2.3 
3 	3.1 	3.2 	3.3 
4 	4.1 		
5 	6 		
7 	8 	9 	

**WARNING:**  
This product may expose you to chemicals such as lead and lead compounds, which are known to the state of California to cause cancer, birth defects, and other reproductive damage. For additional information, visit [www.p65warnings.ca.gov](http://www.p65warnings.ca.gov).

<b>WARNING</b>	<b>AVERTISSEMENT</b>
<p>welding may be hazardous to both the operator and others in the work vicinity. Before operating, read the manual. Failure to apply all of these safety precautions can lead to death.</p>	<p>Le soudage à la baguette peut être dangereux pour l'opérateur et les autres personnes se trouvant à proximité. Avant de travailler, lisez le manuel. Le fait de ne pas appliquer toutes ces mesures de sécurité peut entraîner la mort.</p>
<p>1. Welding sparks might result in an explosion or fire.</p> <p>1.1 Avoid welding near combustible materials.</p> <p>1.2 Keep a fire extinguisher close at hand and ready to use.</p> <p>1.3 As a welding table, never use a drum or any closed container.</p>	<p>1. Les étincelles de soudage peuvent provoquer une explosion ou un incendie.</p> <p>1.1 Évitez de souder à proximité de matériaux combustibles.</p> <p>1.2 Gardez un extincteur à portée de main et prêt à être utilisé.</p> <p>1.3 Comme table de soudage, n'utilisez jamais un baril ou tout autre récipient fermé.</p>
<p>2. Dangerous voltage, Electric Shock or Burn Risk</p> <p>2.1 Put on insulating gloves. Replace damp or damaged gloves. Do not touch the electrode barehanded.</p> <p>2.2 Protect yourself against electric shock by isolating yourself from the work and the ground.</p> <p>2.3 Before maintenance turn off the power. Do not come into contact with any live parts.</p>	<p>2. Tension dangereuse. Risque de choc électrique ou de brûlure.</p> <p>2.1 Mettez des gants isolants. Remplacez les gants humides ou endommagés. Ne pas toucher l'électrode à main nue.</p> <p>2.2 Protégez-vous contre les chocs électriques en vous isolant du travail et du sol.</p> <p>2.3 Avant toute maintenance, coupez l'alimentation électrique. N'entrez pas en contact avec les pièces sous tension.</p>
<p>3. Welding fumes can potentially harmful.</p> <p>3.1 Avoid inhaling fumes.</p> <p>3.2 Avoid working in confined places. Ventilation is necessary to eliminate fumes.</p> <p>3.3 To get rid of the fumes, use forced ventilation or local exhaust.</p>	<p>3. Les fumées de soudage peuvent être potentiellement dangereuses.</p> <p>3.1 Évitez d'inhaler les fumées.</p> <p>3.2 Pour se débarrasser des fumées, utilisez une ventilation forcée ou une aspiration locale.</p> <p>3.3 Évitez de travailler dans des endroits confinés. La ventilation est nécessaire pour éliminer les fumées.</p>
<p>4. Arc rays can cause eye and skin injury.</p> <p>4.1 Wear the proper protective equipment to cover your head, eyes, ears, hands, and body. Button up the shirt collar. Keep noise out of your ears. Wear a welding helmet with the appropriate filter shade.</p>	<p>4. Les rayons d'arc peuvent causer des blessures aux yeux et à la peau.</p> <p>4.1 Portez l'équipement de protection approprié pour couvrir votre tête, vos yeux, vos oreilles, vos mains et votre corps. Boutonnez le col de votre chemise. Empêchez le bruit d'entrer dans vos oreilles. Portez un casque de soudage avec la teinte de filtre appropriée.</p>
<p>5. Get trained.</p> <p>This device should only be operated by qualified individuals. Keep non-qualified people and minors at a safe distance.</p>	<p>5. Se former.</p> <p>Cet appareil ne doit être utilisé que par des personnes qualifiées. Maintenez les personnes non qualifiées et les mineurs à une distance de sécurité.</p>
<p>6. This label should not be removed, destroyed, or covered. Replace if it is missing, damaged, or worn.</p>	<p>6. Cette étiquette ne doit pas être enlevée, détruite ou recouverte.</p> <p>Remplacez-la si elle est manquante, endommagée ou usée.</p>
<p>7. Moving PARTS can bring injury. Avoid touching moving components. Avoid light spots, such as drive rolls.</p>	<p>7. Les pièces en mouvement peuvent provoquer des blessures. Évitez de toucher les composants en mouvement. Évitez les endroits étroits, comme les rouleaux d'entraînement.</p>
<p>8. Welding wire has the potential to cause harm. Never point a gun at the human body, any metal, or any other object.</p>	<p>8. Le fil de soudure peut potentiellement causer des dommages. Ne jamais pointer une arme à feu vers le corps humain, un métal ou tout autre objet.</p>
<p>9. ELECTRIC SHOCK RISK. Keep your hands and other metallic items far from the welding wire and driving components.</p>	<p>9. RISQUE DE CHOC ÉLECTRIQUES. Gardez vos mains et tout autre objet métallique à l'écart du fil de soudure et des composants de</p>
<p><b>AVERTISSEMENT :</b> Ce produit peut vous exposer à des produits chimiques tels que le plomb et les composés de plomb, qui sont connus dans l'Etat de Californie pour causer le cancer, des anomalies congénitales et d'autres dommages à la reproduction. Pour plus d'informations, consultez le site <a href="http://www.p65warnings.ca.gov">www.p65warnings.ca.gov</a>.</p>	



## □Introduction

Thank you for buying our product. In order to get the best performance out of the equipment and ensure the maximum lifespan of its parts, the use and maintenance instructions contained in this manual must be read and strictly complied with, as well as the safety instructions. They will help you to avoid potential hazards that may exist when working with this product or on the worksite. If repairs to the equipment are required, we recommend that our clients contact our service center workshops, as they have the necessary equipment and personnel that are specifically trained and constantly updated. All our machines and equipment are constantly developed and so changes may be made in terms of their construction and features.

## □Description

The **5 PRO 261 MP** is an LCD Panel, intelligent, powerful, and portable welding machine. This unit is capable of Stick welding, MIG welding and TIG welding with a lift start in manual or synergic mode. The combination of synergic control and job programming ability makes this unit user-friendly for less experienced welders looking to perform high quality welds. It features a LCD display which walks the user through setup one step at a time and then automatically adjusts its parameters to meet the required use. It's like having your own personal welding expert right there with you!

This welding machine exhibits versatility in its voltage capabilities. It is capable of operating within a wide range, from 90 volts AC (VAC) to 275 volts AC (VAC). It is the perfect choice for anyone; from a novice to the professional production welder who has speed and quality in mind.

### The principal characteristics of welding unit are:

- ✓ New appearance and new panel design: More trendy and humanized.
- ✓ 5" High-Resolution LCD Display. Intuitive Interface for Precise Welding Parameter Control and Real-Time Feedback.
- ✓ Incorporates Advanced PWM Technology and IGBT Inverters.
- ✓ Active PFC technology for increased duty cycle and energy efficiency.
- ✓ Multi voltage input, Compatible with Extended Power Cords.
- ✓ Multiple Welding Processes in One Machine, MIG/MAG (Metal Inert Gas/Metal Active Gas) with Pulsed Synergic, Dual Pulsed Synergic, and Manual Welding Modes.
- ✓ Advantages of dual pulse welding:
  - Reducing the occurrence rate of pores.
  - Beautiful weld formation.
- ✓ Effortless MIG Welding with Synergic Programs and Dual Pulse.
- ✓ Pre-Programmed Synergic Controls for Aluminum, Mild Steel, Stainless Steel, and CuSi.
- ✓ Job Memory Function. Store and Recall Up to 10 Welding Programs.
- ✓ Selectable Torch Trigger Modes (2T/4T/S4T) and Spot Welding.

- ✓ function parameter adjustment.
- ✓ Versatile Stick (SMAW) Welding for Various Metals, this machine offers advanced features for superior control and performance in Stick Electrode welding:
  - Hot Start: Ensures easier arc initiation.
  - Adjustable Arc Force: Provides precise control over weld penetration and bead profile.
- ✓ Superior TIG Welding with Lift-Arc Start and Advanced Features:
  - Lift Arc Ignition: Protects the tungsten electrode by initiating the arc without a high-frequency spark. This prevents electrode contamination and sticking during ignition, leading to cleaner welds and extended electrode life.
  - 2T/4T Trigger Control: Offers selectable torch trigger modes for user convenience. 2T mode allows for quick starts and stops, while 4T mode enables continuous welding by simply holding the trigger, reducing fatigue during longer welds.
  - Adjustable Down Slope: By adjusting the down slope settings, you can create a smooth crater and prevent tungsten inclusion in the weld pool.
- ✓ Heavy-Duty Internal Wire Feeder, Handles Large Spools Up to 300mm in Diameter.
- ✓ Euro style MIG torch connection.
- ✓ IP21S rating for environmental/safety protection.
- ✓ Optional Integrated Heavy-Duty Industrial Trolley and Water Cooler.
- ✓ Built-in Protection Ensures Machine Longevity.
- ✓ Generator Compatible.
- ✓ Comprehensive 3 Year Warranty.

### Other Features of the Machine (Auto-switching Fan)

The fan may be switched on and off based on the temperature sensed by a thermal sensor. Speed control is an ideal method for matching the delivery of air with the demands of the application. By controlling the fans and not running them continuously, you will be able to provide exactly the right amount of cooling or ventilation for your equipment, while providing real benefits in energy consumption, time between failures, and whole-life costs.

Here are some key benefits of using an auto-switching fan instead of a continuous-working alternative:

**Power Consumption:** A continuously working fan will always consume 100% power when switched on. Using an auto-switching fan reduces power consumption.

**Noise:** Using an auto-switching fan will also reduce noise.

**Life Expectancy:** Running at full speed, a fan will draw the most power and have the greatest power dissipation, which means its motor will be running at its hottest. This primarily affects the wires and the grease in the bearing system, which is the component with the shortest life expectancy. Using an auto-switching fan creates less heat, which will extend the life of the wire and bearings and the longevity of the fan. A longer-lasting fan means a greater interval between service intervals, saving on the cost of a replacement fan and the labor required to replace it.

**Clean parts:** Fan on demand ensures minimum dust and contamination are deposited over the electronics and other parts

of the machine, so we can expect a longer life span for the parts and machines.

**5 PRO 261 MP** is suitable for all positions welding for various plates and profiles. The weldable materials are: Steel, Stainless Steel, Aluminum, Chrome Moly, Titanium, Copper, Brass and the alloys.

## □ Technical Data

The general technical data of the system is summarized in Table 1.

**Table 1**

Model		5 PRO 261 MP					
Process		MIG	Stick	TIG	MIG	Stick	TIG
Single-phase input 50/60 Hz	V	120 V(-15% +10%)			220 V(±15%)		
Primary current @I <sub>2</sub> Max	A	37	35	26.5	37	38.5	27
I <sub>1</sub> eff max	A	27.5	27.5	26.5	30	30	27
Current range	A	30 to 160	20 to 130	10 to 150	30 to 260	20 to 250	10 to 250
Duty cycle @ 100% in 104°F(40°C)	A	130	110	150	230	210	250
Duty cycle @ 60% in 104°F(40°C)	A	160	130	—	260	250	—
Open circuit voltage	V	99	99 (VRD:14V)		99	99 (VRD:14V)	
Output voltage range	V	15.5 to 22	20.8 to 25.2	10.4 to 16	15.5 to 27	20.8 to 30	10.4 to 20
Technology of Adjustment		Manual or Synergic					
Solid Steel Wire Size Range	Inch (mm)	0.030 - 0.045 (0.8 - 1.2)			0.030 - 0.045 (0.8 - 1.2)		
Stainless steel Wire Size Range	Inch (mm)	0.030 - 0.045 (0.8 - 1.2)			0.030 - 0.045 (0.8- 1.2)		
Flux-cored Wire Size Range	Inch (mm)	0.035 - 0.045 (0.9 - 1.2)			0.035 - 0.045 (0.9 - 1.2)		
Aluminum Wire Size Range	Inch (mm)	0.04 - 0.045 (1.0 - 1.2)			0.04 - 0.045 (1.0 - 1.2)		
Maximum wire feeder speed	lpm (m / min)	944 (24)					
Standards		IEC 60974-1, CAN/CSA-E60974-1					
Protection class		IP 21 S					
Insulation class		F					
Wire Feeder Mechanism Material		Metal					
Wire Spool Size	Inch (mm)	8 or 12 (203 or 305)					
Dimensions (D x W x H)	Inch (mm)	26 x 10.2 x 19.2 (660 x 260 x 490)					
Weight	lb. (ka)	59.5 (27)					

## Specifications, Quality control and Test Conditions


The specification of the machine has been tested as International and North American standards in the lab. All the tests have been done in below conditions as CSA C22.2 No. 60974-1:19 Arc welding equipment — Part 1, Welding power sources and International Standard IEC 60974-1.

**The tests are performed at 104 °F (+40°C), Humidity of 50 % @ 104°F (+40°C) and altitude of below 1000 m from sea level.**

**NOTE: CANAWELD** is always striving to produce the best possible products and improving the quality. Therefore, reserves the right to change, improve or revise the specifications or design of this or any product without prior notice. Such updates or changes do not entitle the buyer of equipment previously sold or shipped to the corresponding modifications, updates, improvements, or replacement of such items. The values specified in the table below are optimal values, your values may differ. Individual equipment may vary from the above specifications due in part, but not exclusively, to any one or more of the following: variations or changes in manufactured components, installation and conditions and power grid supply conditions.

## □ Usage Limits (IEC 60974-1)

The use of a welder is typically discontinuous, in that it is made up of effective work periods (welding) and rest periods (for the positioning of parts, the replacement of wire and under flushing operations etc. This welder is dimensioned to supply a I<sub>2</sub> max nominal current in complete safety for a period of work of X% of the total usage time. The regulations in force establish the total usage time to be 10 minutes. The work cycle is considered to be X% of this period of time. When the work cycle permitted is exceeded a trip switch trips, which protects the welding machine's internal components against dangerous overheating and prevents incorrect functioning of the machine (After several minutes the overheat cut-off rearms automatically and the welder is ready for use again (Automatic reset error). This equipment is built to have a protection level of IP 21 S.



## □ How to Lift Up the Machine

You'll need two lifting straps with a capacity exceeding the weight of the machine. Thread each strap through a handle on the welding machine, creating a loop under the machine. Tighten and secure the straps around the handles. You can use buckles, hooks, or other fastening mechanisms depending on your straps. If the weight feels manageable, you might be able to lift the machine with your arms while holding the straps for stability. This is best done with a partner on each side for better balance and

safety. Lifting a heavy object like a welding machine can strain your back and lead to injuries, especially if done incorrectly. Using the trolley reduces the risk of back strain and makes transportation much easier.

**Warning:** do not touch live electrical parts. Disconnect input power cord before moving unit. Place unit on a proper skid and secure in place before transporting with a fork lift or other vehicle.

**Note:** These hoisting and transportation devices conform to local and national standards. Do not use other hoisting and transportation systems.

## □ Open the Packaging

Upon receiving the system:

- Remove the welding generator and all relevant accessories components from their packaging.
- Check that the weld machine is in good condition, if not report any problems immediately to the seller-distributor.
- Make sure all ventilation grilles are open and that no foreign bodies are blocking the air circulation.

## □ Installation and connections

The installation site for the system must be carefully chosen in order to ensure its satisfactory and safe use. The user is responsible for the installation and use of the system in accordance with the producer's instructions contained in this manual. Before installing the system, the user must take into consideration the potential electromagnetic problems in the work area. In particular, we suggest that you should avoid installing the system close to:

- Signaling, control and telephone cables.
- Radio and television transmitters and receivers.
- Computers and control and measurement instruments.
- Security and protection instruments.

Persons fitted with pace-makers, hearing aids and similar equipment must consult their doctor before going near a machine in operation. The equipment's installation environment must comply to the protection level of the frame i.e. IP 21 S (IEC 60529 publication). The system is capable of working in environments where working conditions are particularly hard. This system is cooled by means of the forced circulation of air, and must therefore be placed in such a way that the air may be easily sucked in and expelled through the apertures made in the frame. The equipment must be assembled as follows:

- Connect the welding machine to the utility line.
- Connect up the welding cables.

General requirements for work area:

- Ensure a clear, well lit work area with unrestricted movement for the operator.
- The work area should be well ventilated, as welding emits fumes which can be dangerous.
- Always maintain easy access to the ON/OFF switch of the welder, and the electrical mains supply.
- Do not expose the welder to rain and do not operate in damp or wet locations.

Where welding must be undertaken in environments with increased risk of electric shock, confined spaces or in the

presence of flammable or explosive materials, it is important that the environment be evaluated in advance by an "expert supervisor". It is also recommended that welding in these circumstances be carried out in the presence of persons trained to intervene in emergencies.

## □ Connecting the welding machine to the utility line

Connection of the machine to the user line (electrical current) must be performed by qualified personnel. Before connecting the welding machine to the mains power supply, make sure that rated voltage and frequency correspond to those provided by the mains power supply (see the rating label on welding machine and check input voltage available at site) and that the welding machine's power switch is turned to "OFF". The three pole cable supplied with the system must be used for the connection to the mains power supply. This cable is made up:

- Two conductors that are used to connect the machine to the power supply.
- The third, which is YELLOW GREEN, is used for making the "GROUND" connection.

Connect a suitable load of normalised plug (2p + e) to the power cable and provide for an electrical socket complete with fuses or an automatic switch. The ground terminal must be connected to the ground conducting wire (YELLOW- GREEN) of the supply.


**5 PRO 261 MP** welding machines can be powered by either 110VAC or 230VAC single-phase electrical networks. With a wide input voltage range of 90VAC to 240VAC, this machine offers exceptional versatility and can be adapted to various electrical systems. The machine's output power will be lower when operated on a 110V input compared to 230V.

**IMPORTANT:** DO NOT to connect the machine to a voltage higher than 240 VAC. If the supply voltage continuously exceeds the safe operating voltage range, it will shorten the life of the welding machine.

**Use Adapter 240/120 V If necessary:**



### Receptacles Types:



**Note 1:** Receptacle circuit testers will easily check the continuity of the grounding conductor. Receptacle circuit testers for 120-volt circuits are available at electrical supply or hardware stores; these inexpensive test devices plug into an electrical outlet. Indicator lights show whether the grounding circuit is available at the outlet, as well as other circuit tests. If the test device shows the absence of a ground connection or other circuit problem, call a qualified electrician for assistance. This is a simple test and should be done periodically.

**Consult with a qualified electrician to test circuits greater than 120 volts, installation proper fuses and grounding.**

Table 2 shows the capacity values that are recommended for fuses in the line with delays.

Please note that, before connecting electricity, check the voltage of the network. Check if the circuit breaker or fuse is suitable for the machine.

**Attention:** Do not use **PVC** welding cable. Use **SOOW** or **H07RN-F** or an equivalent.

**Note 2:** Any extensions to the power cable must be of a suitable diameter, and absolutely not of a smaller diameter than the special cable supplied with the machine.

**Note 3:** Motor start fuses or thermal circuit breakers are recommended for this application. Check local requirements for your situation.

**Table 2**

Model	5 PRO 261 MP	
Rated input voltage/frequency (HZ)	1 Phase 120V (-15%, +10%), 50/60 HZ	1 Phase 220 V (±15%), 50/60 HZ
Rated input capacity (KVA)	4.4	8.5
Maximum primary current (A)	37	38.5
Power factor	0.99	
Input protection (A)	A 15 or 20 ampere individual branch circuit protected by time-delay fuses is required. <sup>1</sup>	D45
Recommended cord size (minimum)	12 AWG	
Recommended Extension Cord Length (Maximum)	10 ft.	
Recommended Grounding Conductor Size (Minimum)	12 AWG	

**Improving the Input Supply Network:**

In case the input supply voltage network is not stable, improve it, if possible, Such as:

- Reduce the number of powerful electrical devices operating simultaneously, using the same power supply.
- Increase the cross section of power supply cable in the event of a significant voltage drop. Consult an electrician for the cable cross section calculation.
- If possible, ask your workshop electricity supplier, change the tap of your power transformer network and decrease or increase your network input voltage, and receive a stable voltage for all appliances in your workshop.

**□Connection to Generator**

The machine can be connected to the generator. The THD (Total Harmonic Distortion) of the generator must be less than 6%. Make sure the power of generator is more than the welding machine. A minimum 12KVA generator is required to produce full power at the output. Be careful the power of generator is

continuous duty or maximum and compare it with maximum and power of welding machine in 100% duty cycle.

**□Front and Rear Panel Layout of Welding Machine**

In Fig. A:

**Pos. 1** Fast coupling reverse polarity. In MIG/MAG welding, a fast connector with reversed polarity is used to connect with polarity conversion plug. In TIG (Lift) it is used to connect with TIG torch. In SMAW (stick welding) it is used to connect with ground cable.

**Pos. 2** Fast coupling straight polarity. In MIG/MAG solid wire, it is used to connect with polarity conversion plug. In TIG (Lift) it is used to connect with ground cable. In SMAW (stick welding) it is used to connect with welding cable.

**Pos. 3** Remote connection plug.

**Pos. 4** TIG torch gas outlet fitting connector.

**Pos. 5** Centralized MIG-MAG torch connection.

**Pos. 6** Power supply switch.in the “O” position the welder is off.

In Fig. B:

**Pos. 7** Mains cable.

**Pos. 8** MIG shielding gas inlet, connect with gas cylinder by gas hose.

**Pos. 9** TIG shielding gas inlet, connect with gas cylinder by gas hose.

In Fig. C:

**Pos. 10** MIG Torch Polarity Change Power. In MIG welding, there are two main polarity configurations:

**10.1** Electrode Positive (EP): This is the most common polarity for MIG welding with solid wires. The electrode (welding wire) is positively charged, and the workpiece is negatively charged. This configuration generates a deeper penetration and faster welding speed.

**10.2** Electrode Negative (EN): This polarity is typically used for Flux-cored wires (FCAW), The self-shielding flux in the core requires a negative electrode to function properly.

**Pos. 11** Spool holder.

**Pos. 12** Wire feed tension adjustment.

**Pos. 13** Dual Wire Feed Tension Arms.

**Pos.14** Wire feeder inlet guide.

**Pos.15** Wire drive rollers.

<sup>1</sup> The Effective Input Current should be used for the determination of cable size & supply requirements. See Table 1.






Fig. A




Fig. B





Fig. C

## □ Front Panel Functions and Descriptions


### SMAW Control Panel



1. **Welding Process Button:** Press this button to switch to SMAW welding mode.
2. **L Parameter Knob:** Rotate this knob to adjust the welding current.
3. **R Parameter Knob:** Press this knob to select between Hot Start or Arc Force. Then, rotate the knob to adjust the selected function's value.
  - **Hot Start:** This function provides a temporary boost of welding current at the moment the arc is initiated. This helps overcome the initial high resistance between the cold electrode and workpiece, making arc starting easier. **Setting Range:** 0-10
  - **Arc force:** An SMAW welding power source is designed to produce constant output current. This means with different types of electrode and arc length; the welding voltage varies to keep the current constant. This can cause instability in some welding conditions as SMAW welding electrodes will have a minimum voltage they can operate with and still have a stable arc. Arc Force control boosts the welding power if it senses the welding voltage is getting too low. The higher the arc force adjustment, the higher the minimum voltage that the power source will allow. This effect will also cause the welding current to increase. 0 is Arc Force off, 10 is maximum Arc Force. This is practically useful for electrode types that have a higher operating voltage requirement or joint types that require a short arc length such as out of position welds.

### Lift TIG Control Panel

1. **Welding Process Button:** Press it to enter Lift TIG welding mode.
2. **L Parameter Knob:** Rotate it to adjust welding current. In the function interface, rotate the knob to select parameters like trigger mode and post-flow time.
3. **R Parameter Knob:** Rotate this knob to adjust the parameters displayed on the TIG function interface.
4. **Function Button:** Press this button to enter the function interface for parameter selection and adjustment.



### Function interface:

1. **Trigger mode:** 2T/4T.
2. **Down slope time:** 0-10 seconds.
3. **Post-Flow Time:** 0-10 seconds.




PARAMETER	
MODE	2T
DOWN SLOPE	10.0s
POST FLOW	10.0s

TIG Lift Water

- **2T Trigger Mode:** In 2T mode, you hold the trigger to activate the welding circuit. When you release the trigger, the circuit stops. This mode doesn't require adjustment of start or crater currents. It's suitable for applications like:

- Re-tack welding
- Transient welding
- Thin plate welding



**0: Trigger Activation,** Pressing and holding the gun switch activates the electromagnetic gas valve. This allows the shielding gas to flow, protecting the weld pool from contamination.

**Pre-Gas Flow 0 - t1 (0.1 - 2.0 seconds):** Before the arc ignites, a pre-determined amount of shielding gas flows for a duration between 0.1 and 2.0 seconds. This purges the welding area of any contaminants.

**Arc Ignition and Current Ramp-Up (t1 - t2):** once the pre-gas time elapses (t1), the arc ignites. The welding current then rises from its minimum setting to the desired welding current (Iw or Ib).

**Welding (t2 - t3):** As long as the gun switch is held down (t2 to t3), the arc and welding current are maintained, allowing you to complete the weld.

**Note:** When pulsed mode is selected, the welding current alternates between a base current and welding current. This helps control heat input and improve weld penetration. If pulsed mode is not selected, the machine will continuously output the set welding current value.

**Current Down-Slope (t3):** Upon releasing the gun switch (t3), the welding current doesn't cut off abruptly. Instead, it gradually decreases according to the pre-selected down-slope time setting. This helps prevent crater cracking in the weld pool.

**Arc Termination (t3 - t4):** During the down-slope period (t3 to t4), the current reduces from the set welding current (Iw or Ib) to the minimum welding current setting. This allows the arc to extinguish smoothly.

**Post-Flow (t4 - t5):** Even after the arc extinguishes (t4), shielding gas continues to flow for a user-adjustable post-flow time (0.0 to 10 seconds) set using the front panel knob. This protects the solidifying weld pool from contamination.


**Welding Completion (t5):** Once the post-flow time elapses (t5), the electromagnetic gas valve shuts off, stopping the flow of

shielding gas. This signifies the completion of the welding process.

- **4T Trigger Mode:** In 4T mode, you activate the welding circuit by pulling and then releasing the trigger. To stop welding, simply pull and release the trigger again. This eliminates the need to hold the trigger continuously, making it ideal for longer welds. TIG machines with 4T mode often offer additional current control options. You can pre-set the start current and crater current.

**Start current:** This helps initiate the arc smoothly, especially when welding thicker materials.

**Crater current:** This reduces the welding current at the end of the weld to prevent crater cracking.



### Initiating the Weld (0 - t4):

**Trigger Press (t0):** Pressing and holding the gun switch activates the electromagnetic gas valve. This allows shielding gas to flow, protecting the weld area from contamination.

**Pre-Gas Flow (0 - t1):** For a set time (0.1 to 2.0 seconds), shielding gas purges the area before the arc ignites, ensuring a clean weld.

**Arc Ignition and Current Ramp-Up (t1 - t2):** At t1, the arc ignites. The welding current gradually increases from a starting value (set by the welder) to the desired welding current (Iw or Ib).

**Upslope (t2):** After the initial ignition, the current smoothly ramps up to the final welding current. This upslope time can be adjusted for optimal weld quality.

**Upslope Completion (t2 - t3):** After the initial increase from the start current, the welding current smoothly reaches the final set value (Iw or Ib) during this adjustable upslope time. This helps prevent weld spatter and improves arc stability.

**Welding (t3 - t4):** Once the upslope completes (t3), you can begin welding. During this stage, the gun switch can be released and the set welding current is maintained as you create the weld.

**Note:** When pulsed mode is selected, the welding current alternates between a base current and welding current. This helps control heat input and improve weld penetration. If pulsed mode is not selected, the machine will continuously output the set welding current value.

**Current Down-Slope (t4):** Releasing the trigger again (at t4) initiates a down-slope phase. The welding current gradually decreases according to the pre-selected down-slope time setting. This helps prevent crater cracking in the weld pool by allowing the molten metal to solidify more smoothly.

**Down-Slope to Crater Current (t4 - t5):** During this adjustable down-slope period (t4 to t5), the welding current gradually reduces from the set welding current (Iw or Ib) to a pre-selected crater current. This controlled decrease helps prevent crater cracking in the weld pool as the metal solidifies.


**Crater Current Time (t5 - t6):** This option clarifies that t5 to t6 represents the duration the welding current remains at the pre-set crater current value.

**Arc Shut-Off (t6):** Releasing the trigger again (at t4) initiates the down-slope phase. Once the down-slope period concludes (t6), the arc extinguishes.

**Post-Flow (t6 – t7):** Even after the arc extinguishes, shielding gas continues to flow for a user-adjustable post-flow time (set using the front panel knob). This protects the solidifying weld pool from contamination. The post-flow time can be adjusted on the front panel (t6 onwards).

**Welding Completion (t7):** Once the post-flow time elapses (t7), the electromagnetic gas valve shuts off, stopping the flow of shielding gas. This signifies the completion of the welding process.

## MIG Manual Control Panel



1. **Welding process button:** Press this button to switch to MIG manual welding mode.
2. **L Parameter Knob:** Rotate the knob to adjust the welding wire feed speed. In the function interface, use this knob to select various welding parameters.
3. **R Parameter Knob:** Rotate this knob to adjust the parameters displayed on the welding function interface.
4. **Function Button:** Press this button to enter the function interface for parameter selection and adjustment.
5. **Manual Wire Button**
6. **Gas Check Button**

### Function interface:



### Mode:

2T: Trigger is pressed and held to weld, released to stop.

4T (Latching): Trigger is pulled once to start, then pulled and released again to stop (welding continues while trigger is released).

Spot weld: Single pulse of welding current for creating tack welds.

**Pre-flow time (0-5 seconds):** Time for shielding gas to flow before the arc ignites, purging the area of contaminants.

**Post-flow time (0-10.0 seconds):** Time for shielding gas to flow after the arc extinguishes, protecting the cooling weld pool.

**Burnback (0-10):** Electrode extension length remaining after the arc stops in MIG welding.


Burnback occurs when the welding wire shorts to the molten weld pool. This creates a surge in current, causing the wire to melt excessively. If the wire feed speed can't keep up with the melting rate, the wire thins and eventually separates from the welding torch. This disconnection is what we call Burnback.

**Slow feed (0-5):** Slow wire feeding speed at the start of a MIG weld to improve arc initiation.


This function controls the initial wire feeding speed at the beginning of a weld. It gradually increases the wire feed speed from zero or a very low speed to the set welding speed over a set time frame. This helps to improve arc starts and reduce weld spatter by allowing the arc to establish itself before the full wire feed speed is reached.

**Spool gun (On/Off):** Enables/disables a push-pull mechanism for feeding wire in MIG welding (typically used for long weldments). (the spool gun is offered as an optional component)

**Spot welding time (0.5-10.0 seconds):** Duration of the welding current pulse in spot weld mode.



## MIG (Dual) Pulse control panel



1. **Welding Process Button:** Press this button to switch to MIG (DUAL) pulse welding mode. This mode provides a pulsed welding current for better control and reduced heat input.
2. **L Parameter Knob:** Rotate the knob to adjust the welding wire feed speed. In the function interface, use this knob to select various welding parameters.
3. **R Parameter Knob:** Rotate this knob to adjust the inductance and other parameters displayed on the welding function interface.
4. **Function Button:** Press this button to enter the function interface for parameter selection and adjustment (e.g., pulse frequency, peak current, background current).
5. **Manual Wire Button**
6. **Gas Check Button**

## Function interface:




### Mode:

2T: Trigger is pressed and held to weld, released to stop.

4T (Latching): Trigger is pulled once to start, then pulled and released again to stop (welding continues while trigger is released).

S4T (Special 4T):



Spot weld (for MIG Pulse): Single pulse of welding current for creating tack welds.

### Wire Material:

#### Solid-Cored Wires:

SS (Stainless Steel): Used for welding various grades of stainless steel.

Fe (Steel): Used for welding different types of mild steel and carbon steel.

CuSi (Copper Silicon): Used for welding silicon bronze and similar alloys.

Al-Mg (Aluminum Magnesium): Used for welding wrought aluminum alloys with magnesium content.

Al-Si (Aluminum Silicon): Used for welding cast aluminum alloys with silicon content.

Al (Aluminum): Used for welding pure (or nearly pure) aluminum.

#### Flux-Cored Wires:

SS (Stainless Steel): Used for welding stainless steel with a self-protecting slag layer (may reduce the need for separate shielding gas depending on the specific application).

Fe (Steel): Used for general purpose steel welding with a self-protecting slag layer (may reduce the need for separate shielding gas depending on the specific application)

**Wire Diameter:** 0.8-1.2mm

**Type of Gas:** Ar, 80% Ar+20%CO<sub>2</sub>, 98% Ar+2%CO<sub>2</sub>

**Pre-Flow Time (0-5 seconds):** Time for shielding gas to flow before the arc ignites, purging the area of contaminants.

**Post-Flow Time (0-10 seconds):** Time for shielding gas to flow after the arc extinguishes, protecting the cooling weld pool.

**Burnback (0-10):** Electrode extension length remaining after the arc stops in MIG welding.

Burnback occurs when the welding wire shorts to the molten weld pool. This creates a surge in current, causing the wire to melt excessively. If the wire feed speed can't keep up with the melting rate, the wire thins and eventually separates from the welding torch. This disconnection is what we call Burnback.

**Slow Feed (0-5):** Slow wire feeding speed at the start of a MIG weld to improve arc initiation. This function controls the initial wire feeding speed at the beginning of a weld. It gradually increases the wire feed speed from zero or a very low speed to the set welding speed over a set time frame. This helps to improve arc starts and reduce weld spatter by allowing the arc to establish itself before the full wire feed speed is reached.

**Delta Pulse Current:** 20-200A. This setting is only available in Dual pulse welding mode. It defines the difference between the peak current and the background current used during the welding process.


**Pulse Frequency (0.5-3Hz) [DUAL Pulse Only]:** This setting controls how often the welding current pulses on and off in DUAL pulse mode. It's measured in Hertz (Hz), which signifies the number of cycles per second.

**Pulse Duty Cycle:** This setting is only available in Dual pulse welding mode. It determines the percentage of time the welding current is at the peak current level within each pulse cycle. The remaining time is spent at the background current level.

**Base Current Arc Length:** -10 to +10. (Only be available in Dual pulse welding mode.)

### MIG SYN control panel

The operator simply sets the welding current like MIG welding and the machine calculates the optimal voltage and wire speed for the material type, wire type and size and shielding gas being used. Obviously other variables such as welding joint type and thickness, air temperature affect the optimal voltage and wire feed setting, so the program provides a voltage fine tuning function for the synergic program selected. Once the voltage is adjusted in a synergic program, it will stay fixed at this variation when the current setting is changed. To reset the voltage for a synergic program back to factory default, change to another program and back again.





1. **Welding Process Button:** Press it to select MIG SYN welding mode.
2. **Left Parameter Knob:** Rotate it to adjust wire feeding speed. In functional parameter interface, rotate it to select parameters.
3. **Right Parameter Knob:** Rotate it to adjust parameters.
4. **Functional Button.**
5. **Manual Wire Feed Button.**
6. **Manual Shield Gas Check Button.**


#### Function interface:



1. **Mode :** 2T/4T/ Spot weld.
2. **Wire Material:**
  - SS (Stainless Steel)-Solid Cored
  - Fe (Steel)-Solid Cored
  - Fe (Steel)- Flux Cored
  - CuSi (Copper Silicone)
  - SS (Stainless Steel)-Flux Cored
3. **Wire Diameter:** 0.8mm - 1.2mm
4. **Type of Gas:** CO2, Ar (Argon), 98%Ar+2%CO2, 80%Ar+20%CO2
5. **Pre Flow Time:** 0-5 seconds
6. **Post Flow Time:** 0-10 seconds
7. **Burnback:** 0-10
8. **Slow feed:** 0-5

## □JOB Program Control Panel

The JOB mode allows you to store and recall different welding programs. However, the machine typically comes without any pre-saved programs upon leaving the factory. Therefore, the operator needs to create and save a program before starting a welding job.



1. **JOB Button:**
  - To access the JOB program menu, press and hold the JOB button for three seconds. This menu allows for the creation, editing, and selection of saved welding programs.

- A one-second press of the JOB button (while within the JOB program menu) facilitates the saving of current welding parameters to the chosen JOB program. The display should clearly indicate the currently selected program.

#### 2. **Parameter Display:**

This section serves to display all the currently selected welding parameters that have been adjusted by the operator.

#### 3. **JOB Number Display:**

This display presents the number of the JOB program that is currently selected or loaded.

#### 4. **L Parameter Knob:**

Rotate it to turn the page and press it to delete the parameters.

#### 5. **R Parameter Knob:**

- Rotating the R parameter knob facilitates the selection of a JOB program number from the displayed list.
- Pressing the R parameter knob initiates, the loading of the selected JOB program, consequently applying its associated welding parameters.

## □Instructions for Saving, Activating, and Deleting Memory Channels

### Saving Machine Settings:

- Adjust the welding parameters on the device to your preferred settings.
- Press and hold the JOB button for one second (1s). The device will automatically save the current settings to the first available memory channel.

### Activating a Saved Memory Channel:

- Press and hold the JOB button for three seconds (3s). This action accesses the JOB program menu which allows you to manage saved settings.
- Rotate the R parameter knob to choose the desired memory channel number from the displayed list.
- Press the R parameter knob to load the chosen memory channel's settings. The device will now apply the saved welding parameters.

### Deleting a Saved Memory Channel:

- Press and hold the JOB button for three seconds (3s) to access the JOB program menu.
- Rotate the L parameter knob to highlight the memory channel you wish to delete from the displayed list.
- Delete selected channel by press the L parameter knob.

**Notes:** The device offers a total of 10 memory channels for storing frequently used welding settings.

## □MIG-MAG Techniques


### Definition of MIG Welding

A continuous, consumable wire electrode and a shielding gas are supplied via a welding gun in the semi-automatic or automated arc welding method known as MIG (metal inert gas), often referred to as GMAW (gas metal arc welding) or MAG (metal active gas welding). With MIG welding, a constant voltage, direct current power supply is most commonly utilized. In MIG welding, there are four main metal transfer techniques: short circuit (also

known as dip transfer), globular transfer, spray transfer, and pulsed-spray. Each has unique characteristics as well as associated benefits and drawbacks.

### Short Circuit Transfer


The most popular technique is short circuit transfer, in which the wire electrode is passed constantly through and out of the contact tip of the welding torch. A short circuit results from the wire touching the workpiece. The molten bead splits from the wire's end and forms a droplet that is deposited into the weld pool as the wire heats up and starts to create one. The arc appears constant to the human eye because of this process, which is repeated around 100 times every second.



A short circuit results from the wire touching the workpiece. There is no arc because there is no gap between the wire and the base metal.

Since the wire can't handle the entire current flow, resistance increases, and the wire starts to melt.

The magnetic field that is produced by the current flow starts to squeeze the melting wire, turning it into a droplet.



The pinch separates the droplet as it forms, and it then falls into the weld pool that is currently developing.

When a droplet separates, an arc is formed, and the force and heat of the arc flatten the droplet into the weld pool.

The heat from the arc is reduced by the wire feed speed, and the wire then re-approaches the work to short circuit and complete the cycle.

### Basic MIG Welding

Good weld quality and weld profile depends on the gun angle, the direction of travel, electrode extension (stick out), travel speed, the thickness of base metal; wire feed speed and arc voltage. To follow are some basic guides to assist with your setup.

#### Torch Position - Travel Direction, Work Angle

Typically, torch position or technique refers to the angle and travel direction that the wire is aimed at the base metal. The characteristic of the weld bead profile and degree of weld penetration will depend on travel speed and work angle.

#### Push Technique


The wire is pushed in the direction of the un-melted work surface from the leading edge of the weld pool. With this method, it is possible to see the weld joint and the wire's path into the joint more clearly. When using the push technique, heat is directed away from the weld puddle, allowing for higher travel speeds and a flatter weld profile with light penetration, which is advantageous when welding thin materials. The larger and flatter welds require less time to clean up and grind.

### Perpendicular Technique

This method, which involves feeding the wire straight into the weld, is typically utilized in automated settings or when the circumstances ask for it. In general, a deeper penetration is attained, and the weld profile is taller.


#### Drag Technique

The wire and torch are pulled away from the weld bead. The base metal receives greater heat, deeper melting, more penetration, and a higher, more built-up weld profile as a result of the concentrated arc and heat on the weld pool.




### Travel Angle

The travel angle is the right-to-left angle with respect to the welding direction. An optimal travel angles for controlling the weld pool is between 5° and 15°. An unstable arc state with poor weld metal transfer, little penetration, high levels of spatter, poor gas shield, and a subpar completed weld will result from a travel angle greater than 20°.



### Angle to the Work


The work angle is the torch's forward-backward angle with respect to the work piece. The proper work angle produces a nice bead shape, eliminates undercutting, inconsistent penetration, poor gas shielding, and produces final welds of higher quality.





## Stick Out

Stick out is the length of the un-melted wire sticking out from the contact tip's end. An even current flow, a stable arc, and a consistent stick out of 5 to 10 mm will result in good penetration and even fusion. A too-short stick-out produces an unstable weld pool, produces spatter, and overheats the contact tip. An unstable arc, a lack of penetration, a lack of fusion, and increased splatter are all effects of a too-lengthy stick-out.




## Travel Speed

The speed at which the torch is moved along the weld joint is known as travel speed, and it is typically measured in inches per minute (IPM). The welder's control over the weld pool places a limit on the travel speed, which can vary based on the environment and his or her expertise. Compared to the drag method, push technique allows for faster travel speeds. Additionally, the gas flow must be proportional to the travel speed, rising with faster travel speeds and falling with slower ones. As the material thickness and amperage rise, the required travel speed must also fall.


### Too Fast Travel Speed

If the travel speed is too fast, the weld bead solidifies too quickly, trapping gases inside the weld metal and resulting in porosity. A too-fast travel speed generates too little heat per inch of travel, resulting in decreased penetration and lower weld fusion. Undercutting of the base metal can also happen and an empty groove in the base metal is created, when the travel speed is too fast for molten metal to flow into the weld crater formed by the arc heat.




### Too Slow Travel Speed

A large weld without sufficient penetration and fusion results from a slow travel speed. Instead of penetrating into the base metal, the arc's energy condenses on top of the weld pool. This results in a weld deposit of low quality and a broader weld bead with more weld metal deposited per inch than is necessary.



## Correct Travel Speed


The right travel speed keeps the arc at the weld pool's leading edge, allowing the base metal to melt just enough to produce good penetration, fusion, and wetting out of the weld pool, which results in a high-quality weld deposit.



## Shielding Gas Selection

The gas is used in the MIG process to shield the atmosphere from the wire, the arc, and the molten metal being welded. Without the shielding gas, most metals would react with atmospheric air when heated to a molten state, resulting in weld flaws such as porosity, lack of fusion, and slag inclusions. To shield the welding zone from the atmosphere, the proper gas flow is also crucial.

Always utilize the proper shielding gas. The weld profile produced by CO<sub>2</sub> is thinner and a little bit higher than that produced by an Argon/CO<sub>2</sub> mixed gas because CO<sub>2</sub> is beneficial for steel and gives good penetration. Better weld ability for thin metals and a larger range of setup tolerance on the machine are two benefits of argon CO<sub>2</sub> (argon 80% & CO<sub>2</sub> 20%) mixed gas.



Applications using silicone bronze and aluminum benefit from argon gas at 100% mixture. It gives good weld control and penetration. CO<sub>2</sub> is not recommended for certain metal alloys.

## Wire types and sizes

Use the appropriate type of wire for the base metal you are welding. Use aluminum wire for aluminum, stainless steel wire for stainless steel, and steel wires for steel.

For thin base metals, use wire with a smaller diameter. Use a larger machine and higher wire diameter for thicker materials and be sure your machine is capable of welding those materials. For a starting point, refer to the "Welding Wire Thickness Chart" below as a reference.

STEEL WELDING WIRE DIAMETER CHART						
MATERIAL THICKNESS In. (mm)	RECOMMENDED WIRE DIAMETERS In. (mm)					
	0.024 (0.6)	0.031 (0.8)	0.035 (0.9)	0.040 (1.0)	0.047 (1.2)	0.063 (1.6)
24 Gauge , 0.024 (0.6)						
22 Gauge , 0.031 (0.8)						
21 Gauge , 0.035 (0.9)						
20 Gauge , 0.040 (1.0)						
18 Gauge , 0.047 (1.2)						

16 Gauge , 0.063 (1.6)						
14 Gauge , 0.078 (2.0)						
1 (2.5)						
1/8" , 0.125 ( 3.0)						
0.16 (4.0)						
0.2 (5.0)						
1/4" , 0.25 (6.0)						
5/16" - 0.315 (8.0)						
3/8" , 0.375 (9.5)						
0.55 (14)						
0.7 (18)						
0.86 (22)						
Depending on the amperage capacity of your machine, multi-pass runs, or a beveled junction design may be necessary for material thicknesses of 0.2 in. (5 mm) and higher.						

### Single Pulse MIG Welding

The Single Pulse function allows the welding arc to achieve spray transfer at lower currents and wire feed speeds compared to traditional manual MIG welding. This capability enables faster welding with several advantages:

- **Increased Deposition Rate:** More weld metal is deposited per unit of time due to the higher pulse peak current.
- **Reduced Heat Affected Zone (HAZ):** The lower average heat input from using pulsed current minimizes the area of the workpiece affected by the weld heat.
- **Enhanced Arc Energy Penetration:** The pulsed peak current provides additional energy for deeper weld penetration compared to spray transfer at constantly high currents.

Single Pulse MIG welding is particularly suited for joining:

- **Stainless Steel:** Due to its good control over heat input, this process minimizes the risk of weld discoloration or burning through thinner stainless steel sections.
- **Aluminum Edges or Seams:** Single pulse helps control heat input and improves weld quality in aluminum edge or seam welds.

### Dual Pulse MIG Welding

Dual Pulse MIG welding offers a refined level of control over heat input compared to Single Pulse MIG. This is achieved by utilizing two distinct current levels within the welding cycle:

- **Peak Current:** Delivers a surge of energy to achieve deep weld penetration.
- **Base Current:** Maintains a lower current level to provide arc stability and reduce overall heat input.


#### Benefits of Dual Pulse:

- **Precise Heat Control:** The independent adjustment of peak and base currents allows for fine-tuning heat input, minimizing the risk of warping or burn-through in thin materials.

- **Strong Penetration with Narrow Bead:** The focused heat from the peak current achieves good penetration while the base current helps maintain a narrower weld bead.
- **Smooth Weld Appearance:** Dual pulse minimizes spatter and provides a smoother weld surface, resembling the characteristic "ripple effect" of a TIG weld. This is achieved without the need for complex torch manipulation techniques required in TIG welding.

**Dual Pulse MIG welding is particularly well-suited for:**

- **Aluminum Alloy Welding:** Due to its excellent heat control and ability to create high-quality, narrow welds, Dual Pulse is a preferred choice for welding aluminum alloys. The waveform visually depicts the cycling between the peak and base current levels during the welding process.



### DUAL PULSE FREQUENCY

Pulse frequency, is a crucial setting in Dual Pulse MIG welding. It controls the frequency (cycles per second or Hz) at which the welding current pulses on and off within the welding cycle. This directly affects the resulting ripple pattern and density of the weld bead.

#### Dual Pulse Duty Cycle and Weld Characteristics

Dual pulse duty cycle plays a significant role in controlling the weld penetration profile and overall bead shape in Dual Pulse MIG welding. It determines the proportional relationship between the peak current time (T1) and the background current time (T2) within each pulse cycle.

#### How Duty Cycle Affects the Weld:

**Strong Pulse Time (T1):** Refers to a higher setting for the peak current time. This translates to a longer duration of high heat input during each pulse, promoting deeper weld penetration.

**Low-Frequency Cycle T2 Ratio (cooling):** Indicates a shorter background current time (T2) relative to the peak current time (T1). This reduces the cooling effect between pulses, allowing more heat to build up and contribute to deeper penetration.

## □Preparing the MIG Welder for Operation

### Gas-Shielded Wire (Fig. D)

- **Earth Cable Connection:** Insert the earth cable plug firmly into the negative (-) socket on the machine and twist to secure the connection.
- **MIG Gun Connection:** Plug the MIG welding gun connector into the MIG torch euro-connector located on the front panel of the machine. Tighten the locking nut securely to ensure a proper connection.
- **Polarity Switching Cable Connection:** Insert the polarity switching cable plug firmly into the positive (+) socket on the center tray of the machine and tighten it securely.

- d. **Gas-Shielded Wire Setup:** Securely connect the gas regulator to the gas cylinder. Then, attach the gas line to the regulator outlet. Connect the gas line to the MIG gas inlet connector on the rear panel of the machine.





Fig. D

#### Gasless Wire ( Fig. E )

- Earth Cable Connection:** Insert the earth cable plug firmly into the positive (+) socket on the machine and twist to secure the connection.
- MIG Gun Connection:** Plug the MIG welding gun connector into the MIG torch euro-connector located on the front panel of the machine. Tighten the locking nut securely to ensure a proper connection.
- Polarity Switching Cable Connection:** Insert the polarity switching cable plug firmly into the negative (-) socket on the center tray of the machine and tighten it securely.







Fig. E

- Connect the power cord of the welding machine directly to a grounded electrical outlet.
- Mount the wire spool onto the spool holder. Be mindful that the spool retaining nut utilizes a left-handed thread. Tighten the nut securely in a counter-clockwise direction. Guide the welding wire through the inlet guide tube and onto the drive roller.




- 1: Wire spool hub spring
- 2: Wire spool hub nut
- 3: Location pin



- 4: Wire spool body hole
- 5: Plastic nut


- Thread the welding wire over the drive roller and into the outlet guide tube. Advance the wire approximately 150 mm (millimeters) by pushing it through the guide tube.



Wire Feeding

- Close the top roller assembly and secure the pressure arm with moderate pressure.





5. Remove the gas nozzle and contact tip from the front end of the MIG torch.




6. Press and hold the manual wire feed button to activate wire feeding. This will advance the welding wire through the torch cable and into the torch head.
7. Select a contact tip with a diameter that corresponds precisely to the welding wire diameter. Carefully position the contact tip over the end of the welding wire. Secure the contact tip firmly in the tip holder by tightening it.



8. Fit the gas nozzle to the torch head.



9. Carefully open the gas cylinder valve and set the required gas flow rate.



10. Choose the Required MIG Welding Process.
11. Select torch trigger mode: 2T or 4T.
12. Employ the knobs and buttons on the control panel to adjust and set the required welding parameters.

## □Wire Feed Roller Selection

In MIG welding, achieving a smooth and consistent wire feed is paramount to producing high-quality welds. This section details the role of feed rollers and the significance of proper wire selection and pressure adjustment.

MIG welding machines utilize feed rollers, also known as drive rollers, to mechanically propel the welding wire through the torch

and onto the workpiece. These rollers are designed for specific wire diameters and materials. The grooves machined into their surfaces provide a gripping mechanism for the wire. The top roller in the wire drive unit, referred to as the pressure roller, applies pressure to the wire held within the groove. This pressure is regulated by a tension arm, allowing for adjustments to optimize wire feeding based on the specific wire type. The optimal pressure applied to the wire and the most suitable type of drive roller are directly influenced by the chosen welding wire material and diameter. Selecting the appropriate combination ensures smooth and consistent wire feeding, ultimately leading to superior weld quality.

**Solid Hard Wire Feeding Requirements:** Solid hard wires, such as steel and stainless steel, necessitate drive rollers with a V-shaped groove for optimal grip and wire feeding performance. This groove design offers several advantages for solid wires:

- The V-shape provides a more secure grip on the wire compared to other groove profiles, minimizing slippage during feeding.
- The V-groove allows for the application of higher tension from the top pressure roller without deforming the wire. This is crucial for solid wires as they can handle greater tension due to their superior cross-sectional strength.
- The stiffer nature of solid wires, which resist bending more readily, benefits from the V-groove's guiding effect. This translates to smoother and more consistent wire feeding.

**Soft Wire Feeding Considerations:** Soft wires, such as aluminum, present unique challenges during MIG welding due to their physical properties. This section addresses the specific requirements for feeding soft wires and the advantages of U-shaped drive rollers.

### Challenges of Soft Wire Feeding:

- The U-shaped groove provides a larger contact area with the wire compared to V-grooves. This increased surface area translates to improved grip and traction, facilitating smoother feeding of the softer wire.
- Due to the lower cross-sectional strength of soft wires, excessive tension can cause deformation. U-shaped grooves allow for sufficient wire feeding with minimal tension, minimizing the risk of shape distortion and potential feeding problems at the contact tip.

**Flux-Cored/Gasless Wire Feeding Considerations:** Flux-cored and gasless wires present unique requirements for wire feeding due to their composition and structure. This section discusses the challenges associated with these wires and the advantages of knurled drive rollers.

**Flux-Cored/Gasless Wire Properties:** Flux-cored wires consist of a thin metal sheath filled with fluxing agents and metal compounds. This composite structure necessitates specific considerations during feeding:


- Compared to solid hard wires, flux-cored wires possess lower tolerance for high tension applied by the pressure roller. Excessive pressure can cause the sheath to crush or deform, compromising wire integrity.
- Knurled drive rollers are specifically designed to address the feeding challenges of flux-cored and gasless wires. They offer several advantages:

- The knurled surface, featuring small serrations within the groove, provides a secure grip on the wire without requiring high tension from the pressure roller. This minimizes the risk of crushing or deforming the flux-cored wire.

While knurled rollers offer benefits for flux-cored wire feeding, a potential downside exists:

- Over extended use, the knurled serrations can gradually wear away at the surface of the flux-cored wire. These minute particles may become lodged within the liner, causing friction and potential feeding issues.

U-shaped drive rollers can also be used for flux-cored wires. While they do not offer the same level of grip as knurled rollers, they minimize the risk of wire particles detaching and causing liner clogs. The selection between knurled and U-shaped rollers for flux-cored wires involves a trade-off. Knurled rollers provide a more positive (reliable) feed but may introduce wear particles. U-grooved rollers minimize wear but may require adjusting other feeding parameters for optimal performance.




## □Wire Installation and Set Up Guide

Achieving smooth and consistent wire feeding is paramount in MIG welding, significantly impacting weld quality. Improper wire installation within the wire feed unit is a frequent source of malfunctions in MIG welders. The following guide outlines the essential steps for setting up your wire feeder correctly.


1. Unscrew the spool retaining nut.




2. Identify the tension spring adjuster and spool locating pin.




3. Place the wire spool onto the spool holder, ensuring the spool locating pin on the spool aligns precisely with the corresponding location hole on the holder. Tighten the spool retaining nut firmly to secure the spool in place.




4. Employ wire cutters to sever a section of welding wire from the spool. While cutting, firmly grasp the wire near the cut point to prevent the spool from unwinding uncontrollably. Carefully feed the severed section of wire into the inlet guide tube of the wire feed unit.




5. Feed the wire through the drive roller and into the outlet guide tube of the wire feeder.



6. Engage the Top Pressure Roller and Adjust Wire Tension, Rotate the tension adjustment knob in the designated direction to apply a moderate clamping force to the wire. The goal is to secure the wire firmly without deforming it.



7. Visually confirm that the welding wire feeds through the center of the outlet guide tube without making contact with the sides. If the wire grazes the sides of the guide tube, loosen the locking screw that secures the guide tube's position. Loosen the outlet guide tube retaining nut to allow for slight positional adjustments. Carefully manipulate the guide tube until the wire feeds centrally through it. Once centered, firmly retighten the outlet guide tube retaining nut. Finally, retighten the locking screw to secure the guide tube in its adjusted position.



8. A simple check for the correct drive tension is to bend the end of the wire over hold it about 100mm from your hand and let it run into your hand, it should coil round in your hand



without stopping and slipping at the drive rollers, increase the tension if it slips.

**WARNING:** Must wear gloves.



9. During MIG welding, the weight and rotational speed of the wire spool can generate inertia. This inertia can cause the spool to over-rotate after the wire feed is stopped, potentially leading to the spool continues to spin momentarily after wire feeding ceases. Excess wire may loop over the side of the spool, creating tangles. To address these issues, you can increase the pressure applied by the tension spring located within the spool holder assembly. This can be achieved by manipulating the tension adjustment screw.



## ❑MIG Torch Liner Installation

1. Remove MIG torch front end parts.



2. Remove the liner retaining nut.



3. Carefully pull out and completely remove.



4. Uncoil the New Liner with Care.



5. Carefully feed in the new liner down the torch lead all the way to exit the torch neck.



6. Fit the liner retaining nut and screw only 1/2 way down.



7. Snip the liner off 3mm past the end of the torch neck. (Remove any burrs)



8. Replace the front end parts.



9. Fully screw down the liner retaining nut and tighten.



## ❑MIG Torch Liner Types and Information

### MIG Torch Liners

The liner is both one of the simplest and most important components of a MIG gun. Its sole purpose is to guide the welding wire from the wire feeder, through the gun cable and up to the contact tip.

**Steel MIG Gun Liners:** Steel liners, fabricated from coiled steel wire, are a prevalent choice for MIG guns due to their advantageous properties, the inherent rigidity of steel offers a strong structure for the liner, while maintaining sufficient flexibility to navigate bends and flex during welding operations. This allows for smooth and uninterrupted wire feeding through the gun cable. Solid steel wires benefit most from steel liners as they effectively guide the wire without compromising its shape. The internal diameter of the liner is critical. It should closely match the diameter of the welding wire being used. This ensures smooth feeding and prevents issues like:

- Kinking: Improperly sized liners can cause the wire to bend sharply within the liner, leading to kinks.
- Birdnesting: When the wire kinks or bunches up excessively at the drive rollers, a birdnesting condition occurs, hindering proper wire feeding.

Excessive bending of the welding cable during use should be avoided. This increases friction between the liner and the wire, making it harder to push the wire through and potentially resulting in:

- **Poor Wire Feeding:** Increased friction can disrupt smooth wire delivery.
- **Premature Liner Wear:** Friction caused by tight bends can accelerate wear on the liner.
- **Birdnesting:** Friction from tight bends can contribute to birdnesting issues.


**Maintenance:** Over time, dust, grime, and metal particles can accumulate inside the liner, causing friction and blockages. Regularly cleaning the liner by blowing it out with compressed air is recommended.

#### Selection Considerations for Different Wire Diameters:

**Small Diameter Wires (0.6mm - 1.0mm):** These wires have lower columnar strength (resistance to bending). An oversized liner can cause the wire to wander or drift erratically within the liner, leading to poor wire feeding and premature liner wear.

**Large Diameter Wires (1.2mm - 2.4mm):** These wires possess greater columnar strength. However, it's still crucial to ensure the liner's internal diameter provides sufficient clearance to prevent excessive wear.

**Standardization and Color Coding:** Most manufacturers produce liners sized specifically to match common wire diameters and welding torch cable lengths. Additionally, many manufacturers utilize a color-coding system to simplify liner selection for different applications.



#### Teflon and Polyamide (PA) Liners: Applications and Benefits

Teflon and Polyamide (PA) liners offer distinct advantages over steel liners for specific applications:

##### Teflon Liners:

**Suitable for Soft Wires:** These liners excel at feeding soft wires with low columnar strength, such as aluminum. Their smooth interiors minimize friction and promote stable wire feeding, particularly beneficial for small diameter wires.

**High-Heat Applications:** Teflon's properties make it suitable for welding processes involving high heat, especially when used with water-cooled torches and brass neck liners.


**Abrasion Resistance:** Teflon exhibits good resistance to wear from abrasion, allowing its use with various wire types like silicon bronze, stainless steel, and aluminum.

**Caution Regarding Wire Edges:** It's crucial to meticulously inspect the welding wire's end for sharp edges or burrs before feeding it through the liner. These imperfections can scratch the liner's interior, potentially causing blockages and accelerated wear.

**Polyamide (PA) Liners:** These liners are constructed from carbon-infused nylon. PA liners are particularly well-suited for feeding softer aluminum and copper alloy wires, especially in

push-pull torch applications. PA liners often utilize a floating collet design that enables insertion of the liner all the way to the wire feed rollers for improved wire control.

In essence, Teflon and Polyamide liners address the limitations of steel liners by providing smoother wire feeding for soft wires and improved wear resistance in specific applications.



#### Copper/Brass Neck Liners for High-Heat Applications

In MIG welding processes involving significant heat generation, utilizing a brass or copper wound jumper (also known as a neck liner) at the end of the standard liner offers several advantages:

- The superior thermal conductivity of copper and brass compared to steel liners allows for more efficient heat dissipation, particularly at the critical torch neck area. This helps to mitigate overheating and potential liner damage in high-heat applications.
- The superior electrical conductivity of copper and brass also contributes to a more efficient transfer of welding current to the wire. This can lead to more stable arc characteristics and potentially improved weld quality.

#### Applications:

These neck liners are particularly beneficial for:

- **High-amperage welding:** Processes that utilize high welding currents often generate significant heat.
- **Specific materials:** Welding certain materials, such as thick sections or those with high thermal conductivity (e.g., aluminum), can generate more heat at the torch neck.



#### Recommendations for Gas Selection and Adjustment for MIG Process

##### Gas selection for GMAW process:

**Steel:** One of the most common gas mixtures for MIG welding is a mixture of 75% argon to 25% carbon dioxide known as C25. It works as the best all-purpose shielding gas for carbon steel and produces the least amount of spatter, best bead appearance and won't promote burn-through on thinner metals.

100 % CO<sub>2</sub> provides deeper penetration, but also increases spatter and the bead will be rougher than with 75/25. Mixtures of 80% argon and 20% CO<sub>2</sub> as well as 90% argon and 10% CO<sub>2</sub> are also common.

**Stainless Steel:** Ar+He+CO<sub>2</sub> (for short arc) and 98% Ar+2% O<sub>2</sub> (for Spray arc)

**Flux cored:** 100% CO<sub>2</sub> is economical and has deeper penetration on steel but may be too hot for thin metal. 75% Argon + 25% CO<sub>2</sub> is better on thin steels, produces less spatter and better bead appearance.

**Aluminum:** 100% Argon

**Gas Flow for MIG Process:**

Turn on the shielding gas. Adjust the gas pressure as necessary if the conditions change. Higher gas pressure is required when there is wind or a breeze from a fan. Caution: Excessive gas pressure will cause turbulence around the weld pool. This will cause porosity which will affect the strength of the weld.

#### Recommendation for gas flow adjustment in MIG:

Gas flow, in MIG welding, also varies with the size of the nozzle. For a 1/2-inch nozzle, the flow setting should be around 22-27 CFH. For 5/8-inch nozzle, the types often used in industrial settings; should be around 30-35 CFH and for a 3/4-inch nozzle, 30-40 CFH, should be enough.

Welding process	Recommended shielding gas flow
MAG Welding (CO <sub>2</sub> )	Wire diameter x 11.5 = l/min
MIG Brazing	Wire diameter x 11.5 = l/min
MIG Welding (Aluminum)	Wire diameter x 13.5 = l/min (100 % Argon)

## TIG Welding Procedure

### Application range

Regarding materials, thickness, and welding positions, TIG welding is a versatile welding technique. It enables the production of excellent welded joints. Due to a number of intriguing benefits, the method works better than conventional fusion welding techniques. One of these benefits is its adaptability for a wide range of jobs. TIG welding has several uses and can weld practically any metallic material. Today, stainless, acid-proof, and non-scaling steels, as well as aluminum and nickel alloys, are the most often used materials. The technique is distinguished by the production of weld metal with extremely high purity and surface quality. As a result, the process is utilized when welding quality is critical, such as when making goods for the chemical and power industries, or when welding materials prone to scaling, such as titanium and zirconium. Square butt joints may be welded from one side on plate thicknesses ranging from 0.3 to 4 mm without the need of filler metal. TIG welding is mostly utilized in manual welding, but it is also used in automated welding processes such as automatic tube welding and tube sheet welding. The technique adapts itself wonderfully to automation. TIG procedure can be used to connect almost all types of metallic materials if they are at all suitable for fusion welding. It is also a highly clean procedure that ensures a high-quality welded junction while also producing very little spatter and other contaminants. TIG welding also has the unique benefit that, unlike other procedures that use consumable electrodes, the current and feeding of welding consumables are not related. As a result, the welder is able to add only the necessary amount of welding consumable at any given moment and optimize the current for the welding activity. The method is thus especially well-suited for location welding and welding root passes. Due to these benefits, the TIG method is being employed with success in several fields of industries and trade.

### Special Characteristics


- High quality
- Smooth and even weld surface
- Spatter free
- Slag formation free

### Wilding without Fume


The TIG welding method, like any other welding approach, must be learned first by practice. The following are some broad pointers for putting this plan into action. In many ways, manual TIG welding is similar to the forward technique of gas welding. In both cases, the torch is held in one hand while the filler material is held in the other. In both cases, the "nozzle" is pointed away from the weld spot, and the welder uses filler metal to weld toward the hand with the filler metal. The welder may manage the amount of heat given to the workpiece in this technique by altering the length of the arc.

### DC TIG Welding


During the process, the electrode merely serves as a footing for the arc and must not melt (the melting temperature of tungsten is more than 3300°C). When welding with direct current, the electrode is linked to the power source's negative pole, which creates the least heat. The electrode and the molten pool, throughout the welding process, are shielded by a gas, typically pure argon. Any filler material required is fed in by hand, just like in gas welding. The DC power source utilizes DC (direct current), in which the major electrical component, electrons, move in only one direction, from the negative pole (terminal) to the positive pole (terminal). There is an electrical principle at work in the DC electrical circuit that should always be considered while operating any DC circuit.



A DC circuit always has 70% of the energy (heat) on the positive side. This is important because it decides which terminal the TIG torch will be attached to (this rule applies to all the other forms of DC welding as well). An arc is formed between a tungsten electrode and the metal workpiece during DC TIG welding. An inert gas flow protects the weld region from contamination of the tungsten, molten pool, and weld area. When the TIG arc strikes an inert gas, it is ionized and superheated, altering its molecular structure and converting it to a plasma stream. The TIG arc is the plasma stream that flows between the tungsten and the workpiece and may reach temperatures of 19,000°C. It is a highly pure and focused arc that allows for the controlled melting of most metals into a weld pool. TIG welding allows the operator the most flexibility to weld the widest range of materials, thicknesses, and types. DC TIG welding produces the cleanest weld possible, with no sparks or splatter.



The arc's intensity is proportional to the current flowing from the tungsten. To control the power of the arc, the welder alters the welding current. Thin material typically requires a less strong arc with less heat to melt the material, requiring less current (amps), whereas thicker material requires a more powerful arc with more heat, necessitating more current (amps).




### Lift arc ignition method

In less sophisticated DC welding, the arc can be struck by lightly brushing the electrode on the workpiece. The arc ignites, when the tungsten electrode tip comes into touch with the workpiece. The process is described below.

- Place the tungsten electrode tip on the workpiece with care and push the torch trigger afterwards (a factory set amount of current will flow, regardless of the main current set).
- Invert the torch over the torch gas nozzle edge to create a 2-3 mm gap between the electrode tip and the workpiece. The arc ignites, and the welding current is raised to the start or main current set, depending on the selected operating mode.
- Return the torch to its regular welding position.

To end the welding process, release the torch trigger or push and release (depending on the selected method).



**Lift Arc Ignition Method**

### How to TIG Weld?


Because there are some slight variations between gas and TIG welding, an experienced gas welder who wants to switch to TIG welding must learn a new approach. Managing the filler material, on the other hand, is typically not a problem. A proficient arc welder will find it easier to sustain the arc but will need more skills in accurately applying the filler metal.

### TIG Welding Fusion Technique

Manual TIG welding is sometimes regarded as the most challenging of all welding procedures. Because the welder must maintain a limited arc length, tremendous care and expertise are necessary to avoid electrode contact with the work piece. TIG welding, like Oxygen Acetylene torch welding, usually takes two

hands and requires the welder to manually feed a filler wire into the weld pool with one hand while managing the welding torch with the other. However, some welding involving thin materials, such as edge, corner, and butt joints, can be completed without the need of filler metal.


Fusion welding is the process of melting the edges of metal objects together using just the heat and arc force generated by the TIG arc. Once the arc has been begun, the torch tungsten is maintained in position until a weld pool is formed; a circular movement of the tungsten will aid in the formation of a weld pool of the required size. Once the weld pool is formed, tilt the torch at a 75° angle and advance smoothly and evenly along the connection, fusing the materials together.



### TIG Welding with Filler Wire Technique

In many cases, while welding stainless steel and copper, the filler material can be continuously fed into the pool's edge. However, despite the argon shielding, this approach is not recommended for welding aluminum because the aluminum wire would become so hot that scaling would occur on its surface despite the argon shielding. As the wire melts, it transports oxides into the molten pool to such an extent that the arc's cleaning effect on the oxides would be insufficient, resulting in a poor-quality weld. As a result, the wire is pulled back and forth, with the tip sinking beneath the pool's edge at regular intervals.

The heavier the gauge of the filler material required to fill up the joint, the thicker the material to be welded. As a result, as the electrode tip is fed into the pool, a heavy filler wire may come into contact with it. It is better to move the torch back and forth along the weld in this case. When the arc's heat has adequately fused the weld point's edges, raise the torch 6 to 12 mm above the weld point and plunge the welding wire tip into the molten pool to be melted off. To continue the fusing process, the wire is pushed back, and the flame is pushed ahead along the weld. The flame and the filler wire both move in a rhythmic back and forth motion.




This method is recommended for welding from one side with plate thicknesses more than 6 mm.

The filler material is fed in at the pool's edge and must not come into touch with the electrode tip or enter the arc, as seen in the image. The wire tip, on the other hand, must always be



maintained close to the molten pool. This keeps it within the argon gas envelope that covers the arc and weld pool, preventing surface oxidation scaling as much as possible.

As mentioned before and in many cases, TIG welding requires the addition of filler wire to the weld pool in order to enhance the weld and generate a robust weld. Once the arc has been begun, the torch tungsten is maintained in position until a weld pool is formed; a circular movement of the tungsten will aid in the formation of a weld pool of the required size. Once the weld pool is formed, tilt the torch at a 75° angle and move the torch smoothly and uniformly along the joint. The filler metal is added to the weld pool's leading edge. The filler wire is normally held at a 15° angle and fed into the leading edge of the molten pool; as the torch moves ahead, the arc will melt the filler wire into the weld pool. The wire is fed into the molten pool and withdrawn in a repeated process while the torch is pushed gently and evenly ahead. It is critical to retain the molten end of the filler wire within the gas shield during welding to prevent it from oxidizing and polluting the weld pool.



### TIG Torch

The TIG torch should be as flexible and portable as possible. Therefore, it should be as light as possible to avoid making handling the torch uncomfortable during extended welding sessions. Additionally, it needs to be small enough to allow access in tight spaces. The electrically conducting parts must be designed so that heat buildup does not make the torch unpleasant to wield.

There are TIG torches available with self-cooling capacities of up to 250 amps. When higher amperages are required, water-cooled torches should be used. It is possible to change the head angle to find the least fatiguing working position.



### Shielding gas

Inert gases shield the weld pool from the negative effects of the ambient air because they do not chemically react with it or mix with other chemicals. Argon makes up around 1% of the volume of the atmosphere and is heavier than air. The best and most popular shielding gas for TIG welding is argon because it is quickly ionized and insensitive to changes in arc length.

The electrode and molten pool are mostly shielded by the gas both during welding and afterwards until they have cooled.

Enough gas post-flow time guarantees that the molten metal pool cools off without any contact with ambient air.

The flow rate in liters per minute is used to specify the shielding gas supply. This is defined by the weld pool size, which in turn depends on the electrode diameter, gas nozzle diameter, nozzle distance from the surface of the base material, ambient air flow, and type of shielding gas. As a general guideline, add 5 to 10 liters of shielding gas per minute to the most popular tungsten electrode diameters. Manometers can be used to measure indirect flow rate by positioning them in front of an interconnected nozzle that monitors pressure in relation to flow rate. The manometer's scale is directly calibrated in liters per minute. More particularly, float type meters and measuring devices that directly measure using glass tubes measure the actual protective gas flow rate.

### Shielding Gas for protecting the root of welding

Root gas protects the back of the weld from the effects of air and gives the weld a surface that is resistant to acids and other substances of the kind. Stainless steel, acid-resistant steel, and titanium are examples of materials that need root gas. Pure argon or mixtures of 10% hydrogen and 90% nitrogen are the most often used shielding gases.

### TIG Process Gas Cups

The purpose of the ceramic gas cup is to shield the tungsten and weld pool from oxidation while welding. There are nozzles of various sizes to provide the coverage required for the majority of applications.

The most economical nozzles are made of 90 or 95 percent alumina oxide and are suitable for lower amperage applications. However, these nozzles tend to degrade, break, and come off when used in higher amperage applications since they are not particularly good at withstanding thermal stress.



Lava nozzles are more expensive and more resistant to cracking than alumina oxide nozzles. These nozzles perform effectively in situations requiring medium to high amperage.

Some recommended electrode diameter, cup size and gas flow rate have been shown in the following simplified chart. Recommended values may differ according to the actual welding conditions and other parameters such as welding position, workpiece thickness, and ambient temperature and so on.

Welding Amperage (A)		Recommended Electrode Diameter in. ( mm)	Recommended Cup Size (Diameter)	Gas Flow (Argon) CFH ( L/min)
AC	DC			
5-20	5-20	0.20 (0.50)	Size(3) 11/64 (4.3mm) Size(4) 1/4" ( 6.3 mm) Size(5) 5/16" ( 8 mm)	5-8 (3-4)
20-70	25-75	0.40 (1.00)	Size(4) 1/4" ( 6.3 mm) Size(5) 5/16" ( 8 mm)	5-12 (3-6)
70-150	75-140	1/16 (1.6)	Size(4) 1/4" ( 6.3 mm) Size(5) 5/16" ( 8 mm) Size(6) 3/8" (9.5mm)	7-15 ( 4-7)
135-230	140-240	3/32 ( 2.4)	Size(6) 3/8" (9.5mm) Size(7) 7/16" ( 11.1mm) Size(8) 1/2" (12.7 mm)	10-20 ( 5-10)
225-330	240-350	1/8 ( 3.2)	Size(7) 7/16" ( 11.1mm) Size(8) 1/2" (12.7 mm) Size(10) 5/8" (15.8 mm)	10-25 ( 5-12)
310-430	350-490	5/32 ( 4.00)	Size(8) 1/2" (12.7 mm) Size(10) 5/8" (15.8 mm)	15-30 ( 7-14)
410-530	475-780	3/16 ( 4.8)	Size(8) 1/2" (12.7 mm) Size(10) 5/8" (15.8 mm)	20-40 ( 10-19)

Note: Welding with inverter welding machines often requires less heat input (lower amperage). The recommended parameters are all approximate and are only for manual welding, not automated welding. Test the welds to ensure they meet your requirements.

### Gas Lens

Gas lenses provide better coverage in comparison to the standard Colette bodies. Using a gas lens can reduce gas consumption up to 50%. The electrode stick-out may be increased to 15-20 mm, enabling easier access in small spaces and better welding process monitoring.



### TIG Welding Filler Metal Rod Consumables

TIG welding typically employs rod-shaped welding consumables. Welding consumables are often chosen in accordance with the source metal. However, when specific alloying elements are utilized, the welding consumable must differ from the parent metal for metallurgical reasons. The welding consumable's diameter must be matched to the welding task. This is determined by the thickness of the material and the diameter of the tungsten electrode. Welding rods are typically 1000 mm long and to minimize mistakes, they are labeled individually with the name and/or a trade number.

### Cleaning the welding surface

Before beginning the welding process, it is crucial to properly clean the workpiece's surfaces and the fusion faces for the best welding outcomes. Grease, corrosion, filth, and paint should be removed from the surfaces, and the surface must be bright before welding. Wherever feasible, scale layers should also be eliminated. Frequently, brushing is sufficient, but in some cases, the surface must be processed mechanically, either by grinding or another way. For corrosion-resistant materials, only stainless-steel brushes should be used; otherwise, iron particles on the surface might produce rust. In the case of aluminum, it's crucial that the surface doesn't have a heavy layer of oxide so that pores may form. Use the proper chemicals to clean the welding

surfaces. Be aware that solvents containing chlorine may release toxic vapors.

### Tungsten Electrodes

#### Electrodes for TIG welding

TIG welding normally utilizes four different types of electrodes. They are thorium-alloyed tungsten, zirconium-alloyed tungsten, rare earth-alloyed tungsten, and pure tungsten. Tungsten electrodes are non-consumable and available in a range of sizes; they are constructed of pure tungsten or a tungsten-and-other-rare-earth-element alloy. TIG welding was traditionally performed using pure tungsten electrodes. By alloying this type of electrode metal with thorium or zirconium, several advantages were obtained, including an increase in electron flow, which results in enhanced striking and re-striking and, as a consequence, higher arc stability. Furthermore, alloyed electrodes are more robust, can tolerate higher currents, and are less prone to tungsten inclusions in the weld.

**Pure tungsten (Color Code: Green):** This electrode is made of pure tungsten and has a melting temperature of 3400°C. The electrode tip must be rounded for welding aluminum alloys. Tungsten is a rare metallic element that is used to make TIG welding electrodes. TIG relies on the hardness and high-temperature resistance of tungsten to transfer the welding current to the arc. Although pure tungsten has historically resisted heat better because it rounds out rather than creating tiny nodules, it is no longer the ideal material for AC TIG welding. Due to the properties of pure tungsten in combination with AC mode welding, the tungsten balls up, resulting in a larger arc cone and potential arc wandering. The tungsten can become so hot that it splits or falls off, contaminating the weld puddle, when the pure tungsten ball becomes larger than the tungsten's exterior diameter. Pure tungsten may still be needed for some welding processes. To focus heat into the weld and away from the electrode in these circumstances, this machine with extended balance control and AC frequency modification is useful. However, the operators won't experience all the advantages of TIG inverter technology by utilizing the pure tungsten electrode.

**Alloyed Tungsten Electrodes:** Alloyed tungsten electrodes, also known as rare earth tungsten electrodes, exceed traditional pure tungsten and help to maximize the operation's quality and productivity since they contain components like cerium or lanthanum. The right alloyed tungsten depends on the material being welded, the required amperage, and whether AC or DC welding current is used. Unlike pure tungsten, which tends to ball up, rare earth tungsten keeps its point. Additionally, rare earth tungsten alloyed is a superior choice for AC TIG welding because of features like enhanced balancing control and output frequency that remove more heat from the tungsten to reduce the nodules. It reduces nodules and keeps an electrode pointed by concentrating less heat on the tungsten. Choosing rare earth tungsten electrodes in combination with the advanced square-wave technology has another benefit that allows the use of the smaller tungsten electrodes, which provide more control and a more concentrated arc. Just keep in mind that, it is impossible to compare electrodes made by different manufacturers simply by considering the oxide percentages, because the crucial production factors, such as the distribution and particle size of

the oxide, varies amongst the various producers. The only way to know which tungsten is best for you is to test it out in a real-life experiment. The ends of all tungsten electrodes are color-coded for easy identification. The most common tungsten electrodes are listed below.

**Thoriated (Thorium alloyed) (Color Code: Red):** This electrode is commonly used in DC welding of stainless steel, mild steel, copper, titanium, and other materials. Thorium alloyed tungsten electrodes contain at least 97.30 percent tungsten and about 2 percent thorium. They are one of the most widely used electrodes in DC TIG welding and are favored for their durability and convenience of usage. Thorium, on the other hand, is a low-level radioactive threat, and many users have shifted to other options. In terms of radioactivity, thorium is an alpha emitter, although the hazards are insignificant when it is trapped in a tungsten matrix. Thoriated tungsten should never come into touch with open wounds or cuts. The most serious threat to welders is when thorium oxide enters the lungs. This can occur as a result of welding vapor exposure or swallowing of material/dust during tungsten grinding. For usage, follow the manufacturer's warnings, directions, and the material Safety Data Sheet (MSDS). Although Thoriated tungsten is still the most often utilized electrode in DC TIG applications, most industry professionals strongly advise utilizing Ceriated or Lanthanated electrodes for both AC and DC TIG welding due to radiation-related problems. This type of tungsten alloy is a good all-purpose electrode. It operates well when overloaded with additional amperage and has one of the lowest work functions. The Thoriated offers a roughly 20% increase in current carrying capacity, usually longer lifespan, and better resistance to weld contamination. Compared to pure tungsten or Zirconiated tungsten electrodes, arc beginning is simpler, and the arc is more stable with these electrodes. When welding steel, it is preferable that it keeps a pointed tip design. Because it is challenging to retain the balled end, which is required for AC welding, it is not frequently utilized with AC TIG welding.

**Rare earth-alloyed tungsten (Color Code: Purple and Turquoise):** Rare earth-alloyed tungsten electrodes include a minimum of 98 percent tungsten and up to 1.5 percent Lanthanum, as well as tiny amounts of zirconium and Yttrium. Rare earth-alloyed tungsten electrodes have conductivity comparable to Thoriated electrodes. This often implies that the electrodes may be replaced with Thoriated electrodes without needing substantial welding process adjustments. Superior arc starting, electrode longevity, and overall cost-effectiveness are provided by rare earth alloyed. When comparing the electrodes to 2 percent Thoriated tungsten, rare earth-alloyed requires fewer re-grinding and has a longer overall lifespan. In tests, the electrodes' ignition delay actually improves over time, whereas 2 percent Thoriated tungsten begins to degrade after only 25 starts. Rare earth-alloyed tungsten electrodes operate cooler than 2 percent Thoriated tungsten with comparable energy output, prolonging overall tip lifespan. The electrodes operate well in both AC and DC applications. **They may be used as a positive or negative DC electrode with a pointed end, or they can be balled for use with AC power sources.**

**Ceriated (Color Code: Gray):** Ceriated tungsten electrodes are defined as having a minimum of 97.30 percent tungsten and 1.80 to 2.20 percent cerium. Ceriated tungsten works best in low current DC welding, and typically operates with around 10% less amps than Thoriated material. The Ceriated electrodes show a slower rate of vaporization or burn-off than pure tungsten. They offer great arc starting at low amperages and have proven popular in orbital tube welding and thin sheet metal operations. They are most commonly used to weld carbon steel, stainless steel, nickel alloys, and titanium, and in some situations, they can replace 2% Thoriated electrodes. Ceriated tungsten is ideally suited for lower amperages and should last longer than un-Ceriated tungsten. Thoriated or Lanthanated tungsten is better suited for higher amperage applications. Due to its characteristics, it is often suitable for quick welding sessions or when a fixed number of welds are required before the electrode needs to be changed. This electrode may be used for AC or DC welding; however, it is typically utilized for DC welding because AC welding could cause it to break.

**Lanthanated (Color Code: Black, Gold, and Blue):** Minimum 97.80 percent tungsten and 1, 1.5, or 2 percent of lanthanum are present in Lanthanated tungsten electrodes, which are color-coded in black, gold, and blue, respectively. Lanthanum is not radioactive. These electrodes feature strong arc starting properties, a low burn off rate, high arc stability, and good re-ignition characteristics. Starting and maintaining low current arcs generally require 15% less amps. Lanthanated tungsten has the same conductivity properties as 2% Thoriated tungsten. Lanthanated tungsten electrodes are great for improving welding capabilities. They operate well on AC or DC negative electrodes with a pointed end for DC welding, or they can be balled for use with AC sine wave power sources. Lanthanated tungsten keeps its sharpened edge well, which is useful for welding steel and stainless steel on DC or AC from square or sine wave power sources.

**Zirconiated (Zirconium alloyed) (Color Code: White, and Brown):** Zirconiated tungsten electrodes are composed of at least 99.10 percent tungsten and 0.15 to 0.40 percent of zirconium and it is non-radioactive. This electrode was designed primarily for AC welding; however, it may also be used in DC welding, but AC welding is the most prevalent use. Zirconiated tungsten provides a highly steady arc and is tungsten spitting resistant. Because it preserves a balled tip and is very resistant to contamination, it is perfect for AC welding. It has the same or better current carrying capability than Thoriated tungsten. Zirconium electrodes have a melting point of roughly 3800°C. Zirconiated tungsten electrodes often have welding characteristics halfway between pure and Thoriated tungsten. It is ideal for welding light metals such as aluminum and magnesium.


## Tungsten Electrodes Rating for Welding Currents

Tungsten Diameter In.(mm)	DC Current Amps Torch Negative RED (Thoriated)	AC Current Amps Un-Balanced White (Zirconiated)	AC Current Amps Balanced White (Zirconiated)
0.040 (1.0)	15-80	15-80	20-60
1/16 (1.6)	70-150	70-150	60-120
3/32 (2.4)	150-250	140-235	100-180
1/8 (3.2)	250-400	225-325	160-250
0.157(4.0)	400-500	300-400	200-320

**Note:** Welding with inverter welding machines often needed less heat input (lower amperage). The recommended parameters are all approximate and are only for manual welding, not automated welding. Test the welds to ensure they meet your requirements.

### Tungsten Preparation

A pointed electrode produces a narrower, more concentrated arc than rounded or unprepared tungsten electrodes. This helps welders maintain a constant bead width and prevent distortion by improving arc control and accurately directing heat at the weld junction. As shown, it is critical that the electrode tip be correctly grounded. If the tip is not in good form, there is a high possibility that the arc will become unstable. The tip in the image has a 30° angle, which is ideal for low amperages. However, when the welding current increases, the angle must be increased. The table below illustrates the appropriate electrode tip angles. The tip's extreme point should be ground off since it cannot support high currents, burns off quickly, and may contaminate the weld pool. When welding with alternating current, the electrode tip should be softly rounded. It is enough to lightly bevel the electrode's edge. If the electrode tip becomes drop-shaped during AC welding, the amperage is too high for the diameter of the electrode being used.




Use only diamond wheels for cutting and grinding. While tungsten is a highly hard material, a diamond wheel's surface is even harder, which allows for more precise grinding. Weld inconsistency and weld flaws can be caused by grinding with aluminum oxide or other non-diamond wheels because they can produce jagged edges, irregularities, or poor surface finishes that are not visible to the naked eye.

Welding Current (A)	Electrode Tip Angle (°)
20	30°
20 - 100	60 - 90°
100 - 200	90 - 120°
>200	120°




On the grinding wheel, always be sure to grind the tungsten in a longitudinal orientation. If electrodes are ground across, the electrons have to leap over the grinding marks and the arc might start before the tip and wander because tungsten electrodes are created with the molecular structure of the grain running

lengthwise. The electrons flow constantly and easily to the end of the tungsten tip while grinding lengthwise with the grain. The arc starts straight and stays steady, narrow, and concentrated.



### Electrode Flatted (Truncated) Tip

In precision arc welding, the form of the tungsten electrode tip is a significant process variable. The demand for various benefits will be balanced by a wise choice of tip/flat size. To assist in maintaining the heat created in the welding arc and lessen the chance of tungsten contamination, a truncated (flatted) tip is suggested rather than a sharp point. However, arc wander will be more likely to happen and arc starting will be more challenging the larger the flat, the weld penetration and electrode life will be improved by raising the flat to the highest height that still permits arc initiation and reduces arc wonder. To facilitate arc beginning, some welders continue to grind electrodes to a sharp point. However, they run the danger of reduced welding performance due to tip melting and the potential for the point to detach and fall into the weld pool.



### Tungsten Electrode Grinder

The biggest health risk to welders is inhaling or ingesting thorium oxide dust created by grinding tungsten. In order to prevent such a hazardous situation, the use of the Canaweld Tungsten Electrode Grinder Utensil is highly advised.

The CANAWELD Premium Quality TIG Welding Tungsten Grinder is a time and money investment because it is carefully designed to grind welding electrodes with a precision ground finish for crisp, snappy arc starts, better arc control, clean arc transfer, longer electrode run time, and less tungsten waste. It is made to guarantee the safety of the welders' eyes, fingers, and lungs. To make this happen, this grinder machine comes with a cover plate. See the grinder user manual for further details.



### Electrode Included Angle/Taper - DC Welding

In addition to tip/flat preparation, tungsten electrodes for DC welding should be ground longitudinally and concentrically with diamond wheels to a particular included angle. Different angles result in various arc shapes and provide various weld penetration capacities. The advantages of blunter electrodes with a larger included angle are generally as follows:

- Be More Durable
- Can withstand higher amps without degrading



- Have superior weld penetration
- Have a thinner arc shape.

Smaller included angles and sharper electrodes offer:

- Have a larger arc
- Provide less arc welding
- Have a steadier arc

Weld bead size and form are determined by the included angle. In general, penetration rises, and bead width reduces as the included angle increases.

### Selecting the Size of the Electrode

The following table can be used as a starting point to choose the suitable electrode diameter based on the necessary welding amperage.

Tungsten Diameter in. (mm)	Diameter at the Tip in. (mm)	Constant Included Angle Degrees	Current Range Amps	Current Range Pulsed Amps
0.040 (1.0)	0.0050 (0.125)	12	02 - 15	02 - 30
	0.010 (0.25)	20	05 - 30	05 - 60
1/16 (1.6)	0.020 (0.5)	25	08 - 50	05 - 100
	0.032 (0.8)	30	10 - 70	10 - 140
3/32 (2.4)	0.032 (0.8)	35	12 - 90	12 - 180
	0.045 (1.1)	45	15 - 150	15 - 250
1/8 (3.2)	0.045 (1.1)	60	20 - 200	20 - 300
	0.057 (1.5)	90	25 - 250	25 - 350


**Note:** Welding with the inverter welding machines often needed less heat input (lower amperage). The recommended parameters are all approximate and are only for manual welding, not automated welding. Test the welds to ensure they meet your requirements.

**TIG Welding Parameters:** It is important to keep in mind that just the current is set on the welding equipment when determining the welding settings. The welder controls the arc length, which dictates the arc voltage. Therefore, the arc voltage increases as the arc length does. As a starting point, a welding current that is adequate for welding typically ranges between 40 and 45 amps per millimeter of workpiece thickness.

Workpiece Thickness			Welding Amperage		Filler Rod Size
Inch	mm	Gauge	DC	AC	Inch (mm)
0.020	0.5	24	5-20	5-15	0.040 (1)
0.025	0.6	22	10-35	10-30	0.040 (1)
0.032	0.8	20	20-50	25-45	0.040 (1)
0.040	1	18	25-80	45-60	0.040 (1)
0.051	1.3	16	40-90	50-100	0.040 (1)
0.064	1.6	14	60-100	50-100	0.064 (1.6)
0.091	2.3	11	85-125	90-150	0.064 (1.6) - 0.094 (2.4)
1/8	3.2	8	100-135	125-190	0.064 (1.6) - 0.094 (2.4)
5/32	4	6	125-175	180-200	0.094 (2.4)
3/16	4.8	5	150-225	180-240	1/8 (3.2)

**Note:** Welding with inverter welding machines often needed less heat input (lower amperage). The recommended parameters are all approximate and are only for manual welding, not automated welding. Test the welds to ensure they meet your requirements.

## Joint Forms




### TIG on Stainless Steel (single run welding)

Workpiece Thickness Gauge, in. (mm)	Joint Form	Tungsten Electrode Diameter in. (mm)	Welding Wire Diameter in. (mm)	Argon Gas Flow Rate SCFH (L/min)	Welding Current (DCEP) A	Welding Speed in./min (cm/min)
22, 0.031 (0.8)	Butt joint	0.040 (1)	1/16 (1.6)	10.6 (5)	20-50	26 (66)
20, 0.037 (1.0)	Butt joint	1/16 (1.6)	1/16 (1.6)	10.6(5)	50-80	22 (56)
16, 0.063 (1.5)	Butt joint	1/16 (1.6)	1/16 (1.6)	14.9(7)	65-105	11.8 (30)
	Corner joint	1/16 (1.6)	1/16 (1.6)	14.9(7)	75-125	9.8 (25)
14, 0.078 (2.0)	Butt joint	1/16 (1.6)	3/32 (2.4)	14.9(7)	85-125	11.8 (30)
	Corner joint	1/16 (1.6)	3/32 (2.4)	14.9(7)	95-135	9.8 (25)
11, 1/8 (3.2)	Butt joint	1/16 (1.6)	3/32 (2.4)	14.9(7)	100-135	11.8 (30)
	Corner joint	1/16 (1.6)	3/32 (2.4)	14.9(7)	115-145	9.8 (25)
7, 3/16 (4.8)	Butt joint	3/32 (2.4)	1/8 (3.2)	17 (8)	150-225	9.8 (25)
	Corner joint	1/8 (3.2)	1/8 (3.2)	19.1 (9)	175-250	7.9 (20)

**Note:** Welding with inverter welding machines often needed less heat input (lower amperage). The recommended parameters are all approximate and are only for manual welding, not automated welding. Test the welds to ensure they meet your requirements.

## Installation & Operation for TIG Welding

1. Insert the earth cable plug into the positive socket on the front of the machine and tighten it.
2. Plug the welding torch into the negative socket on the front panel, and tighten it.
3. Connect the torch control cable or the remote pedal control cable to the 9-pin connector on the front panel of the machine.
4. Identify the designated gas outlet on the front panel of the TIG welder. Securely connect the gas line from the TIG torch to the gas outlet on the front panel. Once connected, visually inspect the gas line for any leaks or loose connections.
5. Connect the gas regulator to the Gas Cylinder and connect the gas line to the Gas Regulator. Check for Leaks!



**Fig. F**

6. Identify the quick-lock TIG gas inlet connector on the rear panel of the welding machine. Insert the gas line fitting straight into the quick-lock connector on the machine.
7. The connection of the welding machine's power cable to the electrical outlet on-site should only be performed by a qualified electrician familiar with local electrical codes and safety regulations.
8. With a firm grip, slowly turn the valve on the gas cylinder counter-clockwise to open it. It's recommended to purge the gas line for a short duration to remove any air or contaminants before welding.
9. Select TIG welding mode on the front panel.
10. Your welding machine allows you to choose between two torch trigger operation modes: 2T (Two-Touch) and 4T (Four-Touch).
  - a. 2T Operation (Two-Touch): Squeezing the torch trigger initiates gas flow. Briefly touch the workpiece with the electrode tip and then lift it slightly. This contact initiates the welding arc. Releasing the trigger stops both gas flow and the welding arc.
  - b. A single, brief squeeze of the torch trigger initiates gas flow. The arc does not start at this point. Touch the workpiece with the electrode tip and then lift it slightly. This contact initiates the welding arc. Gas flow continues throughout this process. To stop welding, squeeze the trigger again and release it. This action stops both gas flow and the welding arc.

#### **LIFT ARC DC TIG Operation**

Lift Arc ignition allows the arc to be started easily in DC TIG by simply touching the tungsten to the work piece and lifting it up to start the arc. This prevents the tungsten tip sticking to the work piece and breaking the tip from the tungsten electrode. There is a particular technique called "rocking the cup" used in the Lift Arc process that provides easy use of the Lift Arc function.

1. Select welding current and Down slope Time as required on the front panel. The selected welding current and Down slope Time will show on the screen.
2. Assemble front end parts of the TIG torch making sure they are correctly assembled, use the correct size and type of tungsten electrode for the JOB, the tungsten electrode requires a sharpened point for DC welding.

3. Hold the TIG torch comfortably with the gas cup slightly angled above the weld joint. Maintain a recommended distance between the tungsten electrode and the workpiece (typically 1-2 mm as specified). Refer to your specific tungsten size and material recommendations for the ideal distance. Squeeze the torch trigger briefly to initiate gas flow and welding power.
4. With the gas flowing, gently rock the torch cup back and forth in a small circular motion while keeping the tungsten slightly above the workpiece. Upon completing a rocking motion cycle, momentarily touch the tip of the tungsten electrode to the workpiece and immediately lift the torch slightly to initiate
5. Release the trigger to stop the welding.

## **Recommendations for Gas Selection and Adjustment for TIG Process**

### **Gas selection for TIG Process:**

The three most common shielding gas options for GTAW are 100% Argon, 100% Helium and an Argon/Helium mix. These shielding gases can be used for all materials.

#### **100% Argon:**

Argon is primarily used for GTAW due to its availability, cost and good arc starting characteristics. Argon produces consistent high frequency arc starts due to its lower ionization potential and produces more stable arc than helium.

#### **100% Helium:**

Helium offers faster travel speeds and can be used to produce higher heat inputs due to its higher thermal conductivity. While helium is good for welding thicker materials, it can result in inconsistent arc starting due to its higher ionization potential. Helium is also less available and costs more.

#### **Argon/Helium Mixed:**

An argon/helium mixed is typically used to achieve the higher heat inputs of helium while maintaining the superior arc starts offered by argon. The mix ratio can vary, with most mixes using 25 to 75 percent helium. The higher the helium level, the hotter the arc becomes and the lower the arc ignition performance and stability. To determine the best shielding gas for your application, consider the cost, required heat and high frequency arc starting consistency.

### **Gas Flow for TIG Process**

Optimum gas flow will vary depending on the combination of consumables and atmospheric conditions. GTAW flow rates are typically between 10 and 35 Cubic Feet per Hour (CFH) depending on cup size.

As the shielding gas flow increased, the laminar flow column becomes more turbulent, increasing the risk of contamination.

Set the proper gas flow, which should generally be 15 to 20 cubic feet per hour (CFH) for most applications. Although, the flow rate can be set between 15, 25, or 35 CFH depending on the construction of the consumable and its parts.

As the shielding gas exits the nozzle, it has a different velocity than the atmospheric gases surrounding it. The different velocity and density between these two gas types can cause currents to form, which can potentially shift the shielding gas column from laminar flow (which is desirable) to a turbulent flow (less

desirable). When the flow becomes turbulent, atmospheric gases can be drawn into the shielding gas column, resulting in contamination of the solder and/or tungsten.

**Gas Cups for TIG Process:** D/F Nozzles (also called gas cups) provide a given amount of shielding gas coverage to the weld pool, depending on their size (from 1/4 to 5/8-inch ID). For example, a smaller nozzle provides less gas coverage than a larger nozzle. Nozzles also vary in price and performance.


The most cost effective is 90 or 95% alumina oxide nozzles, which work well for low amperage applications. These nozzles, however, do not withstand thermal shock very well on higher amperage applications and tend to deteriorate or crack and fall off. Lava nozzles cost more than alumina oxide nozzles and are more resistant to cracking. These nozzles work well on medium to high amperage applications.

**WARNING:**


- Use the regulator for the gas and pressure for which it is designed. NEVER use a regulator with any other gas.
- Carefully inspect the regulator for damaged threads, dirt, dust, grease, oil, or other flammable substances. Remove dust and dirt with a clean cloth.
- DO NOT attach or use the regulator if oil, grease, flammable substances, or damage is present! Have a qualified repair technician clean the regulator or repair any damage
- Make sure that the regulator has the correct pressure rating and gas service for the cylinder being used.
- Ensure that the pressure rating of the downstream equipment is compatible with the maximum delivery pressure of the regulator.

## Stick Welding Procedure


Manual metal arc welding, often known as stick welding, is one of the most used kinds of arc welding. A disposable electrode rod or "stick" and the base material are brought together by an electric current to form an arc. The electrode rod is constructed from a material that is compatible with the base material being joined, and it is coated with a flux that emits gaseous vapors that act as a shielding gas and as a coating of slag, as well, to protect the weld region from ambient contamination. The slag that accumulates over the weld metal after welding must be chipped away, and the electrode core itself serves as filler material.



By quickly contacting the electrode to the base metal, the arc is started. At the electrode's end, a molten pool is created as the heat from the arc melts the base metal's surface. The molten pool is where the melted electrode metal is moved across the arc to create the deposited weld metal. A slag that results from the electrode coating covers and shields the deposit. There is a protective gas surrounding the arc and the surrounding areas.



Solid metal wire is the core of manual metal arc (stick) electrodes, which also include a flux covering. The wire diameter and a string of letters and numbers are used to identify these electrodes. The metal alloy and the electrode's intended purpose are identified by the letters and numbers. The metal wire core works as a conductor of the current that maintains the arc. The core wire melts and is deposited into the welding pool. The term "Flux" refers to the coating on a shielded metal arc welding electrode. Numerous distinct tasks are accomplished by the flux on the electrode. Creating a protective slag covering over the weld as it cools, establishing arc characteristics, introducing alloying components, and forming a protective gas surrounding the weld region are some of these. In addition to adding filler metal to the molten pool, covered electrodes have several other uses. The electrode's coating performs most of these extra activities.



## Electrode Selection

Choosing an electrode is typically simple because all that is required is to choose one with a composition that is comparable to the parent metal. However, there are a variety of electrodes available for various metals, each of which has unique characteristics to fit a particular sort of activity. It is advised that you speak with your welding provider to choose the ideal electrode choice.

## Arc Length

The electrode should be carefully scraped on the work to strike the arc until the arc is formed. The smallest arc that provides a satisfactory surface for the weld should be used as the correct arc length, according to a straightforward rule. A too-long arc impairs penetration, causes spatter, and provides the weld a rough surface finish. A too-short arc will cause the electrode to stick and produce poor quality welds. The arc length for down hand welding should generally not be longer than the core wire's diameter.

## Electrode Size

The thickness of the workpiece being welded often determines the size of the electrode, with a thicker section requiring a bigger electrode. The next chart lists the largest electrodes that may be used for different thicknesses based on the usage of a type 6013 all-purpose electrode.

## Welding Current (Amperage)

Arc welding depends on selecting the appropriate current for the task at hand. When the current is regulated too low, it is

challenging to initiate and maintain a constant arc. Beads with a noticeably rounded shape will be deposited due to the electrode's inclination to stick to the work and its poor penetration. A hot electrode undercuts and burns through the base metal while also producing a lot of splatters when there is too much current flowing through it. The maximum current that may be used for a certain operation without destroying the output, overheating the electrode, or producing a rough, spattered surface may be considered as the normal current. The allowable current ranges for a type 6013 general-purpose electrode are listed in the table.

Steel Sheet Thickness in. (mm)	Stick Electrode Rod Diameter in. (mm)	Current Range (Amps)
1/16 - 1/8 (1.6 – 3.17)	3/32 ( 2.4 )	45 - 95
1/8 - 1/4 (3.17 – 6.35)	1/8 ( 3.2 )	75 -130
1/4 - 3/8 (6.35 – 9.5)	5/32 ( 4.0 )	105 -185
3/8 - 1/2 (9.5 -12.5)	3/16 ( 4.8 )	150 - 225

### Electrode Angle

To enable a seamless, equal transfer of metal, the electrode's angle with the work is crucial. The electrode is typically angled between 5 and 15 degrees toward the direction of motion when welding in a horizontal, above, horizontal fillet, or down hand position. The electrode should be at an angle of between 80 and 90 degrees to the workpiece while welding vertically up.

### Travel Speed

The electrode should be moved at a pace that will provide the desired length of run in the direction of the joint being welded. To maintain the proper arc length at all times, the electrode is fed downward at the same time. While excessive travel speeds typically result in arc instability, slag inclusions, and poor mechanical characteristics, excessive travel speeds frequently result in poor fusion, lack of penetration, etc.

### Material and Joint Preparation

The weldable material must be free of any pollutants that might contaminate the weld material and interfere with the arc, such as moisture, paint, oil, grease, mill scale, and rust. Joints may need to be prepared using sawing, punching, shearing, machining, flame cutting, and other techniques depending on the technology used. Edges should always be clean and free of debris. The type of joint will be determined by the application selected.

## □SMAW Welding: Installation & Operation

### 1. Connecting Output Cables:

This welding machine has two output sockets. For Shielded Metal Arc Welding (SMAW), the electrode holder is typically connected to the positive (+) socket, while the ground clamp (which connects to the workpiece) is connected to the negative (-) socket. This configuration is known as Direct Current Electrode Positive (DCEP).

**Important Note:** While DCEP is the most common polarity for SMAW, some electrodes require a different polarity for optimal results. Always refer to the electrode manufacturer's information for the correct polarity setting for your specific electrode. Here's a quick reference:




Fig. G (DCEP)




Fig. H (DCEN)

- **DCEP (Direct Current Electrode Positive):** Electrode connected to the **positive (+) output** socket. This is the most common polarity for SMAW.
  - **DCEN (Direct Current Electrode Negative):** Electrode connected to the **negative (-) output** socket. This polarity is used for specific applications or electrode types.
2. Turn the power source on and press the welding mode button to select the SMAW function.
  3. Set the welding current according to the electrode manufacturer's recommendations for the specific electrode type and size you are using.
  4. Set the Hot Start and Arc Force using the knob. These features can improve your welding experience.
  5. Place the electrode into the electrode holder and clamp tight.
  6. Strike the electrode against the work piece to create and arc and hold the electrode steady to maintain the arc.

### Difference between straight polarity and reverse polarity

Direct Current Straight Polarity (DCSP) Direct Current Electrode Negative (DCEN)	Direct Current Reverse Polarity (DCRP) Direct Current Electrode Positive (DCEP)
Electrode is connected to the negative terminal of the power source and the base metal is connected to the positive terminal.	Base metal is connected to the negative terminal of the power source and electrode is connected to the positive terminal.
2/3 of the total arc heat is generated at the base plate and rest is generated at electrode tip.	2/3 of the arc heat is generated at electrode tip; the rest is generated at the base plate.
Proper fusion of the base metal can be achieved easily. So, it eliminates the lack of fusion and lack of penetration defects.	Due to less heat generation near base plate, incomplete fusion of the base plate may occur.



In case of consumable electrodes, filler metal deposition rate is quite low.	Filler metal deposition rate is high as greater heat portion is generated at electrode tip.
Arc voltage and arc stability does not depend on work material emissivity.	Arc voltage and arc stability significantly depend on work material emissivity.
Arc cleaning action (oxide cleaning) is poor.	Arc cleaning action is good.
Inclusion defects may arise if base plate surfaces are not cleaned properly prior to the welding.	Due to good arc cleaning action, tendency of inclusion defects reduces.
DCSP may cause high distortion/ broader HAZ (Heat Affected Zone) in welded component.	Distortion is less with DCRP and also HAZ (Heat Affected Zone) is narrow.
DCSP is not suitable for welding thin plates.	DCRP is suitable for welding thin plates.
Metals with high melting temperature (such as stainless steel, titanium) can be joined by DCSP.	Metals with low melting temperature (such as copper, aluminum) can be joined by DCRP.

## ❑Welding Circuit: Cables, and Connections

### Welding Cables and the Ampacity:

The electrode cable and the welding clamp cable are important parts of a welding circuit. They must be very flexible and have a tough heat-resistant insulation. Connections at the electrode holder, the welding clamp, and at the power source lugs must be soldered or well crimped to assure low electrical resistance. The cross-sectional area of the cable must be sufficient size to carry the welding current with a minimum of voltage drop. Increasing the cable length necessitates increasing the cable diameter to lessen resistance and voltage drop. The below table lists the suggested American Wire Gauge (AWG) cable size to be used for various welding currents and cable lengths.

**Attention:** Don't use PVC welding cable.

### AMPACITY OF WELDING CABLE

AWG SIZE	100% DT	60%DT	35%DT	20%DT
4	161	168	186	220
2	219	236	270	326
1	255	279	324	397
1/0	297	331	390	482
2/0	346	392	468	583
3/0	400	460	557	700
The numbers are approximate in 25 Celsius degree				

When the ambient temperature differs from 25°C, the rating should be corrected by multiplying it by the appropriate factor below:

Ambient temperature Celsius degree	30	35	40	45
Correction factor	0.96	0.91	0.87	0.82

## Welding Cable Ampacity (Based on size and length (AWG))

	100ft	150ft	200ft	250ft	300ft	350ft	400ft
Ampere (Duty Cycle %)	30m	45m	60m	75m	90m	105m	120m
100 (60% DT)	4	4	2	2	1	1/0	1/0
150 (60% DT)	4	2	1	1/0	2/0	3/0	3/0
200 (60% DT)	2	1	1/0	2/0	3/0	4/0	4/0
250 (60% DT)	1	1/0	2/0	3/0	4/0		
300 (60% DT)	1/0	2/0	3/0	4/0			
350 (60% DT)	1/0	3/0	4/0				
400 (60% DT)	2/0	3/0					
450 (60% DT)	2/0	4/0					
500 (60% DT)	3/0	4/0					
550 (60% DT)	3/0	4/0					
600 (60% DT)	4/0						

**NOTE:** Circuit length includes both welding & ground leads, Duty cycle 60%, Ambient temperature of 40 Celsius Degree, copper conductor and voltage Drop of 4% is considered.

## ❑Accessing Welding Machine Settings

The welding machine offers various adjustable settings like language, unit system, and display brightness. Here's how to access and modify these settings:

- Press and hold the functional parameter key for 3 seconds. This will display the settings menu on the machine's interface.
- Use the left-hand parameter knob (often labeled "L") to navigate through the available settings like language, unit system, and brightness.
- Once you've highlighted a specific setting, use the right-hand parameter knob (often labeled "R") to adjust its value.

## ❑Maintenance

**ATTENTION:** Always disconnect the machine power source before doing any maintenance to avoid personal injury accidents such as electric shock and burns.

**IMPORTANT:** Since the welding machines are fully electronic, removing the dust that is sucked into the machine by the fans is of utmost importance.

In order to achieve correct functioning of the machine, proceed as described:

- Periodic removal of accumulations of dirt and dust inside the equipment using compressed air. Do not point the jet of air directly at the electrical parts as this could damage them.
- Periodical inspection for worn cables or loose connections that could cause overheating.
- Make sure the air circuit is completely free of any impurities and that the connections are tight and free of any leaks. In this connection, inspect the solenoid valve very carefully.
- Check the wire feeder rolls periodically and replace them when wear impairs the regular flow of the wire (slipping etc.)

**Grounding Maintenance:** Over time, corrosive soils with high moisture content, high salt content, and high temperatures can degrade ground rods and their connections. Despite low ground resistance values upon initial installation, these values can

increase if the ground rods are eaten away. If there are intermittent electrical problems, the problem may be related to poor grounding or poor power quality. All grounds and ground connections must be checked annually as a part of normal proactive maintenance plan. Once identified, the problem can be solved by replacing or adding ground rods to the grounding system.

**Welding Clamp Maintenance:** Do not Use if the Welding clamp is damaged or in bad condition. If the welding clamp is not in good condition, this will cause welding current leakage or a drop voltage in welding output, which looks like someone changing the settings on your welder. (If you are doing MIG welding, for example, the wire speed may seem more than adequate, and arc is not stable). Often the first reaction of the operator is to change the machine settings to compensate, rather than fix the real cause of the problem.

There are typically 3 areas of “connection” on a welding clamp that can cause a current leakage/blockage.

1. Cable to the cable lug: Lugs are probably the worst offender here! They can be hard to fit properly, sometimes the cable can be removed from the lug, the lug bolt/terminal may come loose, etc., Use a high-quality, copper tin plated cable lug and a professional crimping tool.
2. Within the clamp itself be careful of broken clamp jaws or worn parts. Use a high-quality welding clamp, Strong spring and other mechanical parts, Current conductive parts made from copper or brass and not Steel alloys at all.
3. Clamp to workpiece connection: A weak clamp spring or improper connection to the workpiece, corroded clamping jaws or low electrical conductivity, particularly if workpiece is rusty, causes poor electrical conduction with it and increase in heat.

Once a “connection” problem in a welding clamp develops, the affected component will then begin to heat up. The heat will then accelerate the original problem, causing the connection to fail further, which will then cause more heat and the cycle to continue.

## TORCH

The torch is subjected to high temperatures and is also stressed by traction and torsion. We recommend not to twist the wire and not to use the torch to pull the welder. As a result of the above the torch will require frequent maintenance such as:

- Cleaning welding splashes from the gas diffuser so that the gas flows freely.
- Substitution of the contact tip when the hole is deformed.
- Cleaning of the wire guide liner using trichloroethylene or specific solvents.
- Check of the insulation and connections of the power cable; the connections must be in good electrical and mechanical condition.

## SPARE PARTS

Original spares have been specifically designed for our equipment. The use of spares that are not original may cause variations in the performance and reduce the safety level of the equipment. We are not liable for damage due to use of spare parts that are not original.

## Regular Maintenance Planning:

Date	Maintenance item
Daily Inspection	<p>Observe that the knobs and switches in the front and at the back of arc welding machine are flexible and put correctly in place. If any knob has not been put correctly in place, please correct. If you can't correct or fix the knob, please replace immediately; If any switch is not flexible or it can't be put correctly in place, please replace immediately! Please get in touch with maintenance service department if there are no accessories.</p> <p>After turn-on power, watch/listen if the arc-welding machine has shaking, whistle calling or peculiar smell. If there is one of the above problems, find out the reason and clear it. If you can't find out the reason, please contact your local service repair station or distributor/Agent.</p> <p>Observe that the display value of LCD is intact. If the display number is not intact, please adjust it. If it still doesn't work, please maintain or replace the display PCB.</p> <p>Observe that the min./max. values on LCD agree with the set value. If there is any difference and it has affected the normal welding results, please adjust it.</p> <p>Check whether the fan is damaged and whether it is normal to rotate or control. If the fan is damaged, please change immediately. If the fan does not rotate after the machine is overheated, observe if there is something blocking the blade. If it is blocked, please clear the problem. If the fan does not rotate after getting rid of the above problems, you can poke the blade by the rotation direction of fan. If the fan rotates normally, the start capacity should be replaced. If not, change the fan.</p> <p>Observe whether the fast connector is loose or overheated. If the arc-welding machine has the above problems, it should be fastened or changed.</p> <p>Observe whether the current output cable is damaged. If it is damaged, it should be insulated or changed.</p>
Monthly Inspection	<p>Using the dry compressed air to clear the inside of arc welding machine. Especially for clearing up the dusts on radiator, main voltage transformer, inductors, IGBT modules, fast recover diodes, PCB's, etc.</p> <p>Check the screws and bolts in the machine. If any is loose, please screw it tight. If it is shaved, please replace. If it is rusty, please erase rust on all bolts to ensure it works well.</p>
Annual Inspection	<p>Check whether the actual current accords with the displaying value. If they did not accord, they should be regulated. The actual welding current value can be measured by and adjusted by plier-type ampere meter. Measure the insulating impedance among the main circuit, PCB and case, if it below 1MΩ, insulation is thought to be damaged and need to change, and need to change or strengthen insulation.</p>

**Note:** Only professional service personnel authorized by us may service the machine!

## □Troubleshooting Table

- Before the welding machines are dispatched from the factory, they have already been tested and calibrated accurately. It is forbidden for anyone who is not authorized by our company to do any change to the equipment!

- Maintenance course must be operated carefully. If any wire becomes flexible or is misplaced, it may be potential danger to user!
- Only professional maintenance staff that is authorized by our company could overhaul the machine!
- Be sure to shut off the Main Input Power before doing any repair work on the welding machine!
- If there is any problem and there is no authorized professional maintenance personnel on site, please contact local agent or the distributor!
- **IMPORTANT:** For safety while maintaining the machine, please shut off the main input power and wait for 5 minutes, until capacitors voltage already drop to safe voltage 36V!
- **Power Supply Troubleshooting**

**Note:** If there is a problem and you can't find the authorized professional maintenance personnel, please contact the local agent or a company branch. If there are some simple machine troubles, you can use the following information from the below table:

No.	Trouble	Reasons	Remedy
1	The breaker is closed, but the power light remains off.	Breaker damaged	Change it
		Breaker damaged	Change it
		Input power damaged	Change it
2	Welding Machine Overheats - Fan Not Functioning	Fan damaged	Change it
		The cable is loose	Screw the cable tight
3	Pressing the gun switch doesn't activate the shielded gas flow.	No gas in the gas cylinder	Change it
		Leaking gas hose	Change it
		Solenoid valve damaged	Change it
4	Gas Flow Only During Test, Not Welding	Control switch damaged	Repair the switch
		Control circuit damaged	Check the PCB
5	Wire-feeder doesn't work, Wire reel doesn't work	Motor damaged	Check and change it
		Control circuit damaged	Check the PCB
6	Wire-feeder doesn't work, Wire reel works	The press wheel is loose, causing the weld wire to skid.	Press it tightly again
		The drive wheel diameter is not compatible with the current weld wire diameter.	Change the wheel
		Damage to the welding wire reel.	Change it
		Wire feed conduit is jammed.	Repair or change it
7	No Arc Strike and No Output Voltage	Welding tip jammed due to weld spatter.	Repair or change it
		Output cable improperly connected or loose.	Screw it down or change it
		Welding machine control PCB damaged.	Check the circuit
8	Welding stopped unexpectedly with alarm light activated.	Welding stopped due to machine self-protection.	Welding Machine Fault: Check for Over-Voltage, Over-Current, Over-Temperature, or Low-

			Voltage with Over-Temperature.
9	Welding current uncontrollable.	The potentiometer damaged	Check or change it
		Welding machine control PCB damaged.	Check the circuit
10	Crater current adjustment is unavailable.	The PCB damaged.	Check it
11	No post-gas	The PCB damaged.	Check it

**Table 3**

## Common Welding Problems

### MIG Welding Troubleshooting

The following chart addresses some of the common problems of MIG welding. In all cases of equipment malfunction, the manufacturer's recommendations should be strictly adhered to and followed.

NO.	Trouble	Possible Reason	Suggested Remedy
1	Excessive Spatter	Wire feed speed set too high	Select lower wire feed speed
		Voltage too high	Select a lower voltage setting
		Wrong polarity set	select the correct polarity for the wire being used - see machine setup guide
		Stick out too long	Bring the torch closer to the work
		Contaminated base metal	Remove materials like paint, grease, oil and dirt, including mill scale from base metal
		Contaminated MIG wire	Use clean dry rust free wire. Do not lubricate the wire with oil, grease etc.
		Inadequate gas flow or too much gas flow	Ensure the shielding gas line is properly connected to the machine, regulator, and torch. Check gas hoses, gas valve, and torch for any restrictions or blockages. Adjust the gas flow meter to achieve a flow rate between 6 and 12 liters per minute (l/min). Visually inspect hoses and fittings for any signs of wear, damage, or leaks. Protect the weld zone from excessive wind or drafts.
2	Porosity - small cavities or holes resulting from gas pockets in weld metal.	Wrong gas	Check that the correct gas is being used
		Inadequate gas flow or too much gas flow	Check the gas is connected, check hoses, gas valve and torch are not restricted. Set the gas flow between 10~15 l/min flow rate. Check hoses and fittings for holes, leaks etc. Protect the welding zone from wind and drafts
		Moisture on the base metal	Remove all moisture from base metal before welding
		Contaminated base metal	Remove materials like paint, grease, oil and dirt, including mill scale from base metal
		Contaminated MIG wire	Use clean dry rust free wire. Do not lubricate the wire with oil, grease etc.
		Gas nozzle clogged with	Clean or replace the gas nozzle

		splatter, worn or out of shape	
		Missing or damaged gas diffuser	Replace the gas diffuser
		MIG torch euro connect O-ring missing or damaged	Check and replace the O-ring
3	Wire stubbing during welding	Holding the torch too far away	Bring the torch closer to the work and maintain stick out of 5-10mm
		Welding voltage set too low	Increase the voltage
		Wire Speed set too high	Decrease the wire feed speed
4	Lack of Fusion – failure of weld metal to fuse completely with base metal or a proceeding weld bead.	Contaminated base metal	Remove materials like paint, grease, oil and dirt, including mill scale from base metal
		Not enough heat input	Select a higher voltage range and/or adjust the wire speed to suit
		Improper welding technique	Keep the arc at the leading edge of the weld pool. Gun angle to work should be between 5 & 15°. Direct the arc at the weld joint. Adjust work angle or widen groove to access bottom during welding. Momentarily hold arc on side walls if using weaving technique.
5	Excessive Penetration – weld metal melting through base metal	Too much heat	Select a lower voltage range and/or adjust the wire speed to suit Increase travel speed
6	Lack of Penetration – shallow fusion between weld metal and base metal	Poor in incorrect joint preparation	Material too thick. Joint preparation and design needs to allow access to bottom of groove while maintaining proper welding wire extension and arc characteristics Keep the arc at the leading edge of the weld pool and maintain the gun angle at 5 & 15° keeping stick out between 5-10mm
		Not enough heat input	Select a higher voltage range and/or adjust the wire speed to suit Reduce travel speed
		Contaminated base metal	Remove materials like paint, grease, oil and dirt, including mill scale from base metal

**Table 4**

### MIG Wire Feed Troubleshooting

The following chart addresses some of the common WIRE FEED problems during MIG welding. In all cases of equipment malfunction, the manufacturer's recommendations should be strictly adhered to and followed.

NO.	Trouble	Possible Reason	Suggested Remedy
1	No wire feed	Wrong mode selected	Check that the TIG/MMA/MIG selector switch set to MIG position
		Wrong torch selector switch	Check that the Wire Feeder/ Spool Gun selector switch is set to Wire Feeder position for

			MIG welding and Spool Gun when using the Spool gun
2	Inconsistent / interrupted wire feed	Adjusting wrong dial	Be sure to adjust the wire feed and voltage dials for MIG welding. The amperage dial is for MMA and TIG welding mode
		Wrong polarity selected	Select the correct polarity for the wire being used - see machine setup guide
		Incorrect wire speed setting	Adjust the wire feed speed
		Voltage setting incorrect	Adjust the voltage setting
		MIG torch lead too long	Small diameter wires and soft wires like Aluminum don't feed well through long torch leads - replace the torch with a lesser length torch
		MIG torch lead kinked or too sharp angle being held	Remove the kink, reduce the angle or bend
		Contact tip worn, wrong size, wrong type	Replace the tip with correct size and type
		Liner worn or clogged (the most common causes of bad feeding)	Try to clear the liner by blowing out with compressed air as a temporary cure, it is recommended to replace the liner
		Wrong size liner	Install the correct size liner
		Blocked or worn inlet guide tube	Clear or replace the inlet guide tube
		Wire misaligned in drive roller groove	Locate the wire into the groove of the drive roller
		Incorrect drive roller size	Fit the correct size drive roller for example; 0.8mm wire requires 0.8mm drive roller
		Wrong type of drive roller selected	Fit the correct type roller (e.g. knurled rollers needed for flux cored wires)
		Worn drive rollers	Replace the drive rollers
		Drive roller pressure too high	Can flatten the wire electrode causing it to lodge in the contact tip - reduce the drive roller pressure
		Too much tension on wire spool hub	Reduce the spool hub brake tension
		Wire crossed over on the spool or tangled	Remove the spool untangle the wire or replace the wire
		Contaminated MIG wire	Use clean dry rust free wire. Do not lubricate the wire with oil, grease etc.

**Table 5**

### DC TIG Welding Troubleshooting

NO.	Trouble	Possible Reason	Suggested Remedy
1	Tungsten burning away quickly	Incorrect Gas or No Gas	Use pure Argon. Check cylinder has gas, connected, turned on and torch valve is open
		Inadequate gas flow	Check the gas is connected, check hoses, gas valve and torch are not restricted.
		Back cap not fitted correctly	Make sure the torch back cap is fitted so that the O-ring is inside the torch body



		Torch connected to DC+	Connect the torch to the DC- output terminal
		Incorrect tungsten being used	Check and change the tungsten type if necessary
		Tungsten being oxidized after weld is finished	Keep shielding gas flowing 10~15 seconds after arc stoppage. 1 second for each 10amps of welding current.
2	Contaminated tungsten	Touching tungsten into the weld pool	Keep tungsten from contacting weld puddle. Raise the torch so that the tungsten is off of work piece 2-5mm
		Touching the filler wire to the tungsten	Keep the filler wire from touching the tungsten during welding, feed the filler wire into the leading edge of the weld pool in front of the tungsten
3	Porosity - poor weld appearance and color	Wrong gas/ poor gas flow/ gas leak	Use pure argon. Gas is connected, check hoses, gas valve and torch are not restricted. Set the gas flow between 6-12 l/min. Check hoses and fittings for holes, leaks et
		Contaminated base metal	Remove moisture and materials like paint, grease, oil and dirt from base metal
		Contaminated filler wire	Remove all grease, oil or moisture from filler metal
		Incorrect filler wire	Check the filler wire and change if necessary
4	Yellowish residue/ smoke on the alumina nozzle & discolored tungsten	Incorrect Gas	Use pure Argon gas
		Inadequate gas flow	Set the gas flow between 10-15 l/min flow rate
		Alumina gas nozzle too small	Increase the size of the alumina gas nozzle
5	Unstable Arc DC during welding	Torch connected to DC+	Connect the torch to the DC- output terminal
		Contaminated base metal	Remove materials like paint, grease, oil and dirt, including mill scale from base metal.
		Tungsten is contaminated	Remove 10mm of contaminated tungsten and re grind the tungsten
		Arc length too long	Lower torch so that the tungsten is off of the work piece 2-5mm
6	Arc Wander in DC TIG Welding	Poor gas flow	Check and set the gas flow between 10-15 l/min flow rate
		Incorrect arc length	Lower torch so that the tungsten is off of the work piece 2-5mm
		Tungsten incorrect or in poor condition	Verify the correct tungsten electrode type for your material and application. If necessary, replace the electrode. Then, grind a fresh point approximately 10mm from the tip for optimal arc performance.
		Poorly prepared tungsten	Grind marks should run lengthwise with tungsten, not circular. Use proper grinding method and wheel.

7	Difficulty initiating or maintaining a stable arc in DC TIG welding.	Contaminated base metal or filler wire	Remove contaminating materials like paint, grease, oil and dirt, including mill scale from base metal. Remove all grease, oil or moisture from filler metal
		Incorrect machine set up	Check machine set up is correct
		No gas, incorrect gas flow	Check the gas is connected and cylinder valve open, check hoses, gas valve and torch are not restricted. Set the gas flow between 10-15 l/min flow rate
		Incorrect tungsten size or type	Check and change the size and or the tungsten if required
		Loose connection	Check all connectors and tighten
		Earth clamp not connected to workpiece	Connect the earth clamp directly to the work piece wherever possible

**Table 6**

### Stick Welding Troubleshooting Guide

The following chart addresses some of the common problems of SMAW welding. In all cases of equipment malfunction, the manufacturer's recommendations should be strictly adhered to and followed.

NO.	Trouble	Possible Reason	Suggested Remedy
1	No arc	Incomplete welding circuit	Verify Ground Connection, Inspect Cable Connections
		Wrong mode selected	Check the SMAW selector switch is selected
		No power supply	Verify power supply. Ensure the machine is turned on
2	Porosity – small cavities or holes resulting from gas pockets in weld metal	Arc length too long	Shorten the arc length
		Work piece dirty, contaminated or moisture	Remove moisture and materials like paint, grease, oil and dirt, including mill scale from base metal
		Damp electrodes	Use only dry electrodes
3	Excessive Spatter	Amperage too high	Decrease the amperage or choose a larger electrode
		Arc length too long	Shorten the arc length
4	Weld sits on top, lack of fusion	Insufficient heat input	Increase the amperage or choose a larger electrode
		Work piece dirty, contaminated or moisture	Remove moisture and materials like paint, grease, oil and dirt, including mill scale from base metal
		Poor welding technique	Use the correct welding technique or seek assistance for the correct technique
5	Lack of penetration	Insufficient heat input	Increase the amperage or choose a larger electrode
		Poor welding technique	Use the correct welding technique or seek assistance for the correct technique

		Poor joint preparation	Check the joint design and fit up, make sure the material is not too thick. Seek assistance for the correct joint design and fit up
6	Excessive penetration - burn through	Excessive heat input	Reduce the amperage or use a smaller electrode
		Incorrect travel speed	Try increasing the weld travel speed
7	Uneven weld appearance	Unsteady hand, wavering hand	Use two hands where possible to steady up, practice your technique
8	Distortion – movement of base metal during welding	Excessive heat input	Reduce the amperage or use a smaller electrode
		Poor welding technique	Use the correct welding technique or seek assistance for the correct technique
		Poor joint preparation and or joint design	Check the joint design and fit up, make sure the material is not too thick. Seek assistance for the correct joint design and fit up
9	Electrode welds with different or unusual arc characteristic	Incorrect polarity	Change the polarity, check the electrode manufacturer for correct polarity

**Table 7**

## □Welding Machine Error Codes











This table lists common error codes for your welding machine and their corresponding meanings. If you encounter an error code, consult your user manual for specific troubleshooting steps.

Error Type	Error code	Description
Thermal relay	E01	Over-heating (1st thermal relay)
	E02	Over-heating (2nd thermal relay)
	E03	Over-heating (3rd thermal relay)
	E04	Over-heating (4th thermal relay)
	E09	Over-heating (Program in default)
Welding machine	E10	Phase loss detected.
	E11	Machine indicates no water.
	E12	No gas
	E13	Under voltage
	E14	Over voltage
	E15	Over current
	E16	Wire feeder overload detected.
Switch	E20	Faulty button on control panel when machine is turned on.
	E21	Other issues observed on the control panel when powering on the machine.

	E22	Torch malfunction detected upon powering on the machine.
	E23	Torch fault detected during welding operation.
Accessory	E30	torch disconnected - Reconnect securely.
Communication	E40	Faulty connection between wire feeder and power source
	E41	Communication error

**Table 8**

## □Meaning of graphic symbols on machine

	System for use in environments with increased risk of electroshock
	Product suitable for free circulation in the European Community
	Dangerous voltage
	Grounding protection
	Positive pole snap-in connector
	Negative pole snap-in connector
	Warning!
	Before using the equipment you should carefully read the instructions included in this manual
	Danger! Parts moving
	It is forbidden to use gloves

## ❑Wiring Diagram

